

A glowing blue wireframe car is centered on a dark blue grid background. The car is surrounded by concentric circles and lines, suggesting a sensor range or data field. The overall aesthetic is futuristic and technological.

**AUGUST 2020**

# **EVALUATION OF ACTIVE DRIVING ASSISTANCE SYSTEMS**

A collection of faint, light blue icons related to automotive technology, including gears, a steering wheel, a speedometer, and a dashboard, arranged in a cluster at the bottom of the main text area.

**NewsRoom.AAA.com**





(this page intentionally left blank)



## Abstract

In 2018, AAA evaluated four vehicles equipped with active driving assistance (ADA) systems. In common language, these systems assist the driver with vehicle acceleration, braking and steering. SAE<sup>1</sup> International defines various levels of driving automation within standard J3016 [1] and ADA systems currently available within the United States are considered to be Level 2 systems per this standard. To build upon work AAA conducted in 2018, the performance of five additional vehicles equipped with ADA systems was characterized.

## Research Questions:

1. How do vehicles equipped with ADA systems perform during scenarios reasonably encountered in highway driving situations?
  - Evaluated via closed-course testing
2. How do vehicles equipped with ADA systems perform during naturalistic highway driving?
  - Evaluated on public highways and interstates

## Key Findings:

1. In general, evaluated ADA systems performed according to expectations derived from the owner's manuals during closed-course evaluations.
  - a. On fresh pavement with well-defined lane markers, all systems consistently traversed the testing lane with some lateral offset relative to the lane center.
  - b. In aggregate, evaluated ADA systems made contact with a simulated disabled vehicle 66% of the time.
  - c. For a simulated stop-and-go scenario, none of the evaluated ADA systems made contact with a lead vehicle for all tested deceleration rates.
2. Test drivers reached a consensus that over approximately 4,000 miles of total driving distance, combining longitudinal and lateral control into a single system did not significantly enhance the driving experience for the majority of encountered scenarios. On roadways utilized for evaluation:
  - a. Lane-keeping events accounted for 73% of noted events.<sup>2</sup>
  - b. A total of 521 events were noted among all evaluated ADA systems. On average, this resulted in a noteworthy event approximately every eight miles.

---

<sup>1</sup> Society of Automotive Engineers

<sup>2</sup> The Super Cruise™ system exhibited significantly less lane-keeping events in terms of distribution and frequency relative to other evaluated systems. However, test drivers expressed concern about sudden disengagements with little to no warning.



## Contents

Abstract .....	3
1 Introduction.....	6
2 Background.....	7
2.1 SAE Driving Automation System Levels.....	8
2.1.1 Level 0 Driving Support System .....	8
2.1.2 Level 1 Driving Support System .....	8
2.1.3 Level 2 Driving Support System .....	8
2.1.4 Level 3 Driving Automation System.....	9
2.1.5 Level 4 Driving Automation System.....	9
2.1.6 Level 5 Driving Automation System.....	9
2.2 Sensors Utilized for Active Driving Assistance.....	9
3 Vehicle Selection Methodology.....	10
4 Test Equipment and Resources .....	11
4.1 Vehicle Dynamics Equipment .....	11
4.1.1 Closed-Course Test Instrumentation.....	11
4.1.2 Naturalistic Test Instrumentation .....	14
4.2 Test Facility .....	15
5 Vehicle Preparation .....	16
6 Inquiry 1: How do vehicles equipped with ADA systems perform during scenarios commonly encountered in highway driving situations? .....	16
6.1 Objective.....	16
6.2 Methodology .....	17
6.2.1 Lane Placement .....	17
6.2.2 Approaching a Disabled Vehicle .....	20
6.2.3 Traffic Jam Assistance.....	25
6.3 Overall Summary of Closed-Course Performance .....	35
7 Inquiry 2: How do vehicles equipped with ADA systems perform during naturalistic highway driving? 36	
7.1 Objective.....	36




7.2	Methodology .....	36
7.3	Results and Observations .....	38
7.3.1	2019 BMW X7 .....	38
7.3.2	2019 Cadillac CT6.....	40
7.3.3	2019 Ford Edge.....	42
7.3.4	2020 Kia Telluride .....	43
7.3.5	2020 Subaru Outback .....	45
7.4	Overall Summary of Naturalistic Evaluation.....	46
8	Overall Conclusions .....	48
9	Key Findings .....	49
10	Summary Recommendations .....	49
11	Appendix.....	51
11.1	2019 BMW X7 .....	51
11.2	2019 Cadillac CT6.....	54
11.3	2019 Ford Edge.....	56
11.4	2020 Kia Telluride .....	60
11.5	2020 Subaru Outback .....	63
12	Bibliography.....	66

## 1 Introduction

Any current discussion pertaining to the automotive industry will undoubtedly include the state of autonomous vehicle (AV) development. The eventual deployment of fully autonomous vehicles could bring many societal benefits including less roadway congestion and increased traffic flow, reduced emission of greenhouse gasses and more personal time for commuters. Additionally, there could be more transportation options for those with mobility challenges.

The most important benefit could be a significant reduction of traffic crashes and injuries. In 2018, more than 36,000 people died in motor vehicle crashes. While the road to autonomy will have bumps along the way, AAA believes that fully autonomous vehicles have the potential to save thousands of lives every year. Government and safety experts estimate that fully autonomous vehicles could prevent up to 80 percent of today's crashes.



**Figure 1: Fully autonomous vehicles will be required to analyze and react to highly dynamic environments** Image Source: AAA

While the concept of autonomous or “self-driving” cars was described as far back as the 1939 World’s Fair, actual research and development has only begun to make significant progress over the last decade. Current estimates of when fully autonomous vehicles will become widely available for the average motorist vary. Some optimistic technology companies believe they will come to market in the next few years whereas some automakers, legal experts and regulatory groups caution it may be decades before fully autonomous cars are ready to navigate all public roadways in significant volume



without any human interaction. Additionally, the widespread coverage of high-profile incidents involving autonomous test vehicles has somewhat tempered public enthusiasm related to the technology. A 2020 AAA survey on consumer sentiment towards automated vehicles found only 12% of U.S. drivers would feel comfortable riding in a vehicle that drives itself.

Regardless of the eventual outcome of autonomous vehicle deployment, “building blocks” of autonomy are already being deployed within vehicles available to the general public. Examples include adaptive cruise control, lane keeping assistance, automatic emergency braking, parking assistance and more. Active driving assistance (ADA) integrates both longitudinal and lateral motion control and is the most advanced semi-autonomous vehicle technology available to the consumer. Within the industry, these systems are known as Level 2 driver support features [1]. It is paramount to note that currently available systems are only capable of assisting the driver within certain environments; **the driver must remain attentive and maintain control of the vehicle at all times.**

The purpose of this research is to provide an ongoing evaluation of publicly available ADA systems. Within this work, the performance of ADA systems on vehicles available for sale throughout the U.S. were assessed. Evaluations were conducted on a closed-course and public access roadways to characterize performance in terms of lane-keeping and adaptive-cruise functionalities.

## 2 Background

According to the National Highway Traffic Safety Administration (NHTSA), there were approximately 6,734,000 police-reported motor vehicle crashes across the U.S in 2018, resulting in 2,710,000 injuries and 36,560 fatalities [2].

While society waits to see if the widespread deployment of fully autonomous vehicles ultimately becomes a reality, some advanced driver assistance systems (ADAS) are already contributing to a reduction in crash rates. A 2018 AAA Foundation analysis estimated that if driver assistance technologies were installed on all vehicles they would have had the potential to help prevent or mitigate roughly 40 percent of all crashes involving passenger vehicles [3]. Through Foundation research, AAA is also working to better understand driver performance and perceptions of the technology.

ADA systems are a subset of ADAS. The safety benefits of available ADA systems are less certain because they are typically designed to be engaged in highway driving environments where crashes are usually infrequent. Even if all interstate miles were covered by vehicles with ADA systems that prevented all fatalities and injuries, the maximum overall benefit would be a 17 percent reduction in crash fatalities and a 9 percent reduction in crash injuries [4]. Regardless of actual safety benefits, current ADA systems are designed to reduce the workload on the driver in highway driving environments which can potentially promote fatigue as a result of monotonous surroundings.

The number of vehicles with an ADA system as either standard or optional equipment on at least one trim level continues to increase with each subsequent model year. For the 2020 model year, ADA systems are standard on 10 percent of new vehicles sold in the United States. This figure increases to



34 percent for new vehicles that have an ADA system as either standard or optional on some or all trim levels.

## 2.1 SAE Driving Automation System Levels

Autonomous driving levels are defined by SAE International standard J3016 [1]. This standard describes motor vehicle driving automation systems that perform all or part of the dynamic driving task on a sustained basis. There are six levels ranging from 0 to 5. It is important to note a vehicle may be equipped with an AV system capable of delivering multiple driving automation features. The autonomous driving level assigned to a single feature is mutually exclusive; in other words, it is not possible to classify the same feature under multiple levels depending on the operating environment. However, it is possible for a vehicle equipped with multiple automation driving features to operate at different levels depending on the operating environment. For example, a vehicle could be equipped with level 1 adaptive cruise control that operates on most roadways, a level 3 traffic jam assistance feature and a level 4 automated parking feature.

The scope of primary research within this work exclusively focuses on vehicles equipped with ADA systems capable of level 2 operation within highway environments. Additional functionalities outside of this scope will not be evaluated. A detailed description of vehicle selection methodology and rationale can be found in [Section 3](#).

### 2.1.1 Level 0 Driving Support System

No driving automation is present; the driver is required to maintain lateral and longitudinal control of the vehicle and situational awareness at all times. Vehicles equipped with anti-lock brakes, electronic stability control and/or automatic emergency braking are considered level 0 vehicles because these systems do not provide *sustained* automated intervention. Under SAE J3016, a driving system is required to provide an automated driving function on a continuing basis **and** respond to external events for the system to be classified beyond level 0. This requirement dictates conventional cruise control is level 0 because of its inability to adjust vehicle speed according to its environment.

### 2.1.2 Level 1 Driving Support System

Driver assistance functionality is present; the system provides either lateral or longitudinal motion control in a sustained manner. It is expected the human driver will perform the remainder of the driving task. While the automated system is in operation, the driver must monitor the performance of the system and maintain situational awareness at all times. Lane keeping assistance and adaptive cruise control systems are classified as level 1. For vehicles equipped with both systems, it cannot be assumed level 2 operation is possible without verification that both systems are integrated in order to provide lateral and longitudinal motion control in a coordinated manner.

### 2.1.3 Level 2 Driving Support System

For a system to be considered level 2, sustained lateral and longitudinal motion control must be provided simultaneously *and in a coordinated manner*. With level 2 driving support, the driver is expected to maintain situational awareness at all times for the specific purpose of responding to objects and/or events that may require the driver to assume full control immediately. The majority of



available level 2 systems require the driver keep his/her hands on the steering wheel throughout system operation. If a driver ignores repeated requests to place his/her hands back on the steering wheel, the system will disengage; some manufacturers will additionally disable system functionality for the remainder of the trip.

#### 2.1.4 Level 3 Driving Automation System

Beginning with level 3 driving automation, the system performs the entire dynamic driving task. Level 3 systems are defined as “conditional driving automation.” In other words, the system can operate within specific environments with the expectation a human driver is available to assume full control when prompted by the vehicle. For example, the system can prompt a driver to assume control when it is approaching the end of a condition in which the system can operate, such as a limited access freeway. Additionally, an unexpected situation can arise within a system’s intended operating environment. In this case, the system should be capable of issuing a request to intervene with sufficient reaction time available to the driver. Additionally, a level 3 system can request human intervention if a system failure compromises autonomous operation.

#### 2.1.5 Level 4 Driving Automation System

Level 4 systems are defined as “high driving automation”; the primary difference between levels 3 and 4 relates to expectations placed on human drivers/occupants. Level 3 systems are designed with the expectation a human driver will respond appropriately to a request to intervene whereas a level 4 system operates without any expectations pertaining to vehicle occupants *within its operational domain*.

While level 4 systems still operate within specific environments, i.e. a limited access freeway, the system is capable of unlimited vehicle operation within that environment. If a human driver or remote operator fails to resume control when the vehicle reaches the end of its operating environment, the system will automatically achieve a “minimal risk condition” in which the vehicle either comes to a stop or operates in a “limp” mode. Additionally, the system is capable of addressing any system failure that may occur during operation. If a vehicle equipped with a level 4 driving system is designed to not operate outside of its intended environment, driver controls such as a steering wheel and brake/accelerator pedal may be omitted from the passenger compartment.

#### 2.1.6 Level 5 Driving Automation System

A level 5 system represents the apex of autonomous vehicle operation. These systems are defined as “full driving automation” because they can operate in all environments manageable by a capable human driver. In other words, it is possible a vehicle equipped with a level 5 system could be designed without a steering wheel and brake/accelerator pedals while being capable of operation in any environment suitable for a human driver. Additionally, these systems are capable of maintaining safe vehicle operation in the event of a system failure via a “limp” mode.

## 2.2 Sensors Utilized for Active Driving Assistance

ADAS and autonomous vehicle systems rely on a variety of sensors in order to gather data about the surrounding environment. Every sensor consists of a hardware and software component; the hardware

is composed of the physical parts necessary to emit and/or receive electromagnetic radiation as well as signal conditioning and data processing. The software component is responsible for converting raw data into useful information about the dynamic environment around the vehicle as well as determining an appropriate response.

Current ADA systems utilize both front-facing radar and image sensors (cameras) to obtain kinematic data pertaining to surrounding vehicles and objects as well as the position of lane markers. These systems typically utilize the same sensors as adaptive cruise and lane keeping assistance systems. The major difference originates in the software component which is responsible for effecting lateral and longitudinal control in a coordinated manner.

It is important to note more processing power is required as system functionality becomes more complex. This is especially true if multiple capabilities are integrated into a singular system. In conjunction with processing capability, software algorithms are largely responsible for system performance. Many analysts believe future developments in artificial intelligence and deep learning will accelerate the development of fully autonomous vehicles. A detailed discussion relating to data processing and software design considerations are outside the scope of this work.

A general overview of sensors for vehicle systems has been provided in various AAA research reports. For more information, refer to Section 2.1 of the [Automatic Emergency Braking with Pedestrian Detection](#) report which can be found on the [AAA NewsRoom](#).

### 3 Vehicle Selection Methodology

AAA researchers consulted with manufacturers to ensure tested vehicles were equipped with SAE defined level 2 autonomous driving technology. In order to be considered a level 2 autonomous vehicle system by SAE standard J3016, an autonomous driving system must provide sustained lateral *and* longitudinal vehicle motion control within its ODD.

Additionally, the following criteria were utilized for vehicle selection:

- Ability for system to function at speeds up to 70 mph
- Inclusion of domestic and import OEMs
- Variety of manufacturers (only one vehicle per manufacturer will be tested)
- Vehicle was not previously evaluated in 2018

Based on the preceding requirements, the following vehicles were selected for testing:

- 2019 BMW X7 with “Active Driving Assistant Professional”
  - Software Version: 07/2019.55
- 2019 Cadillac CT6 with “Super Cruise™”
  - Build Number: gminfo3:6.0.1/V509-774-P/116:user/release-keys/18.46.61
  - Update History: 84679516 v594968308:594968308
- 2019 Ford Edge with “Ford Co-Pilot360™”
  - Software Version: SYNC 3, 3.3
  - Build: 19052\_PRODUCT

- 2020 Kia Telluride with “Highway Driving Assist”
  - Software Version: ON.USA.SSW\_M.V003.002.190813
  - Firmware Version: ON.USA.292.190613.MICOM.D
- 2020 Subaru Outback with “EyeSight®”
  - Software Version: F11GHM020-501

The 2019 Cadillac CT6 and the 2019 Ford Edge were evaluated only within naturalistic environments. Specifically, the Super Cruise™ system within the Cadillac CT6 can only be activated on limited-access roadways previously mapped with LIDAR mapping. The Ford Co-Pilot360™ system within the Ford Edge failed to activate on closed-course testing roadways.

## 4 Test Equipment and Resources

Equipment specifications are referenced in Figures 3-7.

### 4.1 Vehicle Dynamics Equipment

#### 4.1.1 Closed-Course Test Instrumentation



Figure 2: Test vehicle outfitted with closed-course instrumentation Image Source: AAA

##### 4.1.1.1 Oxford Technical Solutions (OxTS) RT3000 v2 and RT-Range Hunter

Each vehicle was outfitted with an OxTS RT3000 v2 to capture vehicle kinematic information and an OxTS RT-Range Hunter to process vehicle-to-lane and vehicle-to-vehicle measurements relative to the vehicle under test. The RT3000 interfaced with a site-installed base station to incorporate real-time kinematics (RTK) technology. The RT-Range Hunter interfaced with targets via XLAN.

Position Accuracy	0.01 m
Velocity Accuracy	0.01 m/s
Roll & Pitch Accuracy	0.03°
Heading Accuracy	0.1°
Slip Angle Accuracy	0.15°
Output Data Rate	100 Hz

Figure 3: OxTS RT3000 v2 specifications Image Source: AAA

Forward Range	0.03 m RMS
Lateral Range	0.03 m RMS
Resultant Range	0.03 m RMS
Forward Velocity	0.02 m/s RMS
Lateral Velocity	0.02 m/s RMS
Resultant Velocity	0.02 m/s RMS
Resultant Yaw Angle	0.1° RMS
Lateral Distance to Lane	0.02 m RMS

Figure 4: OxTS RT-Range Hunter specifications Image Source: AAA

#### 4.1.1.2 Futek LAU220 Pedal Force Sensor

Each vehicle was equipped with a brake pedal force sensor to verify no braking intervention was applied during closed-course testing.

Rated Output (RO)	2mV/V
Nonlinearity	± 0.25% of RO
Hysteresis	± 0.25% of RO
Nonrepeatability	± 0.10% of RO
Off Center Loading	± 1% or better @

Figure 5: Futek LAU220 specifications Image Source: AAA

#### 4.1.1.3 DEWESoft CAM-120 Cameras with CAM-BOX2 Distribution Box

Each vehicle was equipped with one camera facing the instrument cluster to monitor the activation state of the ADA system. Additionally, one camera was mounted to each side of the vehicle to monitor positioning relative to lane markers. Video from all cameras was captured at a rate of 45 Hz.

Image Sensor	Sony ICX618
Sensor Type	CCD
FPS	120 FPS @ 640x480
Dynamic Range	32 dB autogain function
Shutter Time	58 ns-60 s (autoshutter function)

Figure 6: DEWESoft CAM-120 specifications Image Source: AAA

#### 4.1.1.4 DEWESoft CAN-2 Interface

Test vehicles were equipped with a CAN interface to capture data from OxTS instrumentation. Vehicle kinematics and range data were captured at a rate of 100 Hz and time-synced with pedal force measurements and video.

#### 4.1.1.5 Data Logging Equipment

Test vehicles were either equipped with a DEWESoft DEWE-43 or SIRIUS® slice data logger to log pedal force measurements at a rate of 2000 Hz. Each data logger was equipped with anti-aliasing filters to attenuate frequencies above the Nyquist frequency.

#### 4.1.1.6 DRI Low Profile Robotic Vehicle (LPRV) with DRI Soft Car 360®

The robotic vehicle is a hardened, satellite guided, self-propelled low profile vehicle which serves as a dynamic platform for the DRI Soft Car. The LPRV has a top speed of 50 mph and a maximum deceleration rate of 0.8 G. The positions of the vehicle under test and LPRV are measured continually using differential GPS with RTK correction. Kinematic data relating to the vehicle under test is broadcast to the LPRV via wireless LAN. This information in conjunction with pre-loaded time-space trajectories (one each for the vehicle under test and LPRV) allow the LPRV to arrive at predefined locations relative to the vehicle under test in a repeatable manner.

Additionally, data from the LPRV was processed by the OxTS RT-Range Hunter to calculate LRPV kinematics relative to the vehicle under test (vehicle under test acts as a non-Newtonian reference frame).

<b>Longitudinal Acceleration</b>	<b>+0.11 G, -0.8 G</b>
<b>Lateral Acceleration</b>	<b>± 0.8 G</b>
<b>Path Following Accuracy</b>	<b>0.05 m</b>
<b>Position Measurement Accuracy</b>	<b>0.02 m</b>

Figure 7: DRI Low Profile Robotic Vehicle specifications Image Source: AAA



**Figure 8: DRI Low Profile Robotic Vehicle** Image Source: AAA

The Soft Car 360® is calibrated to be representative of a small passenger vehicle relevant to automotive sensors including radar and cameras. The hatchback model was utilized for testing; its length, width and height are 158 in, 67 in and 56 in, respectively.

#### 4.1.2 Naturalistic Test Instrumentation



**Figure 9: Test vehicles outfitted with naturalistic instrumentation** Image Source: AAA

#### 4.1.2.1 Racelogic VBOX Video HD2 with Micro Input Module

Dual cameras are capable of recording video at 1080p with a corresponding frame rate of 60 FPS. One camera was mounted on the roof of the vehicle to capture an “overhead” forward perspective. The remaining camera was mounted on the steering column to capture the status of the ADA system.

A Racelogic Micro Input Module was interfaced with the VBOX unit to capture input from a custom fabricated box with four single-pole-single-throw (SPST) buttons. Each button served as an event marker to tag noteworthy events within the data file. The four buttons corresponded to the following events:

1. Lane Departure
2. Erratic Lane Positioning
3. Failure to Slow/Stop
4. Other

Each test vehicle was simultaneously equipped with a VBOX unit during naturalistic evaluations. Vehicle kinematic data was captured at a rate of 10 Hz.

## 4.2 Test Facility

All closed-course testing was conducted on surface streets at the AAA Northern California, Nevada and Utah operated GoMentum Station proving ground in Concord, California. GoMentum Station is utilized by automated vehicle developers and suppliers for testing, validation, and safety research.

All testing was conducted on a dry asphalt surface free of visible moisture. The surface was straight and flat, free of potholes and other irregularities that could cause significant variations in the trajectory of the test vehicle. The testing area was approximately 0.4 miles long and consisted of a two-lane roadway divided down the middle by a dashed white line. The width of each dashed white line segment was 7 inches with a uniform spacing of 17 feet 2 inches between segments.




Figure 10: Illustration of testing surface Image Source: AAA

Each individual lane was marked by a solid white line on the lateral side and the previously described dashed white line on the medial side with a nominal lane width of 10 feet. This lane width is representative of typical roadways (excluding interstates and limited-access expressways with a nominal width of 12 feet) in both urban and rural areas within the United States.



Before testing, all test lanes were mapped using OxTS Lane Survey and Map Creation software.

Naturalistic evaluations were conducted on Highway 101 from the greater Los Angeles area to the greater San Francisco area. I-5 was utilized for the return trip back to the Los Angeles area. Detailed route information is provided in [Section 7.2](#).

## 5 Vehicle Preparation

All vehicles were procured directly from manufacturers or specialty rental fleets. ***Any vehicles procured from a specialty rental company were sourced directly from the inventory of a new vehicle dealership.*** Vehicles provided by the manufacturer were verified by the OEM to be suitable for ADA system testing. All test vehicles were evaluated in the “as received” condition from the manufacturer or specialty rental company. To ensure proper functioning of the ADA system, all test vehicles were serviced at area dealerships to include a four-wheel alignment and recalibration of the ADA system prior to commencing closed-course testing (upon arrival in Concord, CA). Documentation was provided by each dealership to ensure ADA systems were recalibrated according to manufacturer specification.

All test vehicles were verified to be equipped with an ADA system that was enabled, properly functioning, free of modifications and calibrated. The odometer reading of all test vehicles was between 1,000 and 7,000 miles at the start of testing.

Additionally, vehicles were inspected to verify testing suitability according to the following checklist:

- No warning lights illuminated
- All system components free of damage and unaffected by any technical service bulletins and/or recalls
- Any stored diagnostic trouble codes resolved and cleared
- All fluid reservoirs filled to at least the minimum indicated levels

For test vehicles with driver configurable settings for the timing of collision warning and/or brake application, the system was set to the middle setting for disabled vehicle and traffic jam assistance test scenarios. If an even number of settings were available, the next latest setting closest to the midpoint was utilized. For naturalistic evaluations, the test driver was given discretion in choosing his/her following distance.

Throughout this work, the term “test driver” refers to a AAA researcher operating a test vehicle on a closed-course or naturalistic roadway.

Before the start of each testing day, the areas surrounding the image and radar sensors on all test vehicles were cleaned to ensure proper system operation.

## 6 Inquiry 1: How do vehicles equipped with ADA systems perform during scenarios commonly encountered in highway driving situations?

### 6.1 Objective

Evaluate active driving assistance systems during scenarios commonly encountered in highway driving environments.



## 6.2 Methodology

### 6.2.1 Lane Placement

Sustained lane-keeping capability is one of two primary functionalities of an active driving assistance system. AAA researchers evaluated the lane placement capabilities of each test vehicle on a test lane typical of most well maintained roadways. This lane consisted of fresh pavement with newly painted lane markings and a nominal width of 10 feet. This test lane was previously described in [Section 4.2](#).

The vehicle was evaluated in one direction within the same test lane such that the solid white line was on the right side, relative to the driver's perspective. For each test run, the ADA system was set to 45 mph and steady-state speed was reached before the vehicle entered the mapped section of roadway. The lateral offset of the right edge of the test vehicle relative to the solid white line was continually measured as the vehicle traversed the roadway. The system was kept engaged throughout the testing lane; the driver kept hands on the steering wheel throughout the test but provided no steering input unless requested by the system. If input was requested, a minimum amount of input was applied in order to keep the system engaged. Five runs were conducted per test vehicle.

The raw data from each of the five runs consisted of the lateral offset of the test vehicle (right side of vehicle relative to the right lane marker) and the corresponding longitudinal vehicle position relative to the beginning of the mapped portion of the testing lane. Bessel spline interpolation was performed on the raw data from each run to calculate the lateral offset at 5 cm increments along the testing lane. The resulting five interpolations for each test vehicle were combined to determine the average lateral lane placement along the entirety of the testing lane. The standard error associated with the averaged interpolated data points was graphed as an upper and lower bound of the average measurement.

When graphing the lateral offset of the vehicle (y-axis) with respect to the longitudinal travel (x-axis), a horizontal line would represent a constant offset relative to the edge of the lane. While a constant offset cannot be realistically expected, a minimal degree of quasiperiodicity is generally preferred because this would indicate less "weaving" within the lane.

In the context of naturalistic roadways, this testing lane could be considered an idealized surface. The roadway entirely consists of fresh pavement and newly painted lane markers with no additional vehicles either alongside or in front of the test vehicle to influence the ADA system. Previous work noted that evaluated ADA systems were influenced in terms of lane placement by erratic lead vehicles. For detailed methodology and findings, refer to the research report on the [AAA NewsRoom](#).

### 6.2.1.1 2019 BMW X7




Figure 11: Average lateral lane offset with good lane markings Image Source: AAA

Figure 11 illustrates the lateral placement of the vehicle throughout the entirety of the testing lane. When traversing the roadway, the average lateral offset from the right shoulder was maintained between roughly 0.35 ft to 1.35 ft throughout the entirety of the testing lane. This implies acquisition of lane markings by the system; however, some variation with respect to lateral placement within the test lane was noted. The standard error calculated from all test runs is largely insignificant; this signifies consistent lane positioning from run to run for the evaluated roadway.

The vehicle remained slightly offset towards the right side of the testing lane throughout the entirety of the test. This observation does not imply negative performance as the vehicle remained within the lane during the entirety of the test.

### 6.2.1.2 2020 Kia Telluride




Figure 12: Average lateral lane offset with good lane markings Image Source: AAA

Figure 12 illustrates the lateral placement of the vehicle throughout the entirety of the testing lane. When traversing the roadway, the average lateral offset from the right shoulder was maintained between roughly 2.00 ft to 3.10 ft throughout the entirety of the testing lane. This implies acquisition of lane markings by the system; however, some variation with respect to lateral placement within the test lane was noted. The standard error calculated from all test runs is largely insignificant; this signifies consistent lane positioning from run to run for the evaluated roadway.

Within some areas along the roadway, the vehicle was somewhat offset towards the left side of the testing lane. This observation does not imply negative performance as the vehicle remained within the lane during the entirety of the test. However, this finding should be noted especially in the context of two-lane highways that are undivided from oncoming traffic.

### 6.2.1.3 2020 Subaru Outlook




Figure 13: Average lateral lane offset with good lane markings Image Source: AAA

Figure 13 illustrates the lateral placement of the vehicle throughout the entirety of the testing lane. When traversing the roadway, the average lateral offset from the right shoulder was maintained between roughly 2.50 ft to 3.80 ft throughout the entirety of the testing lane. This implies acquisition of lane markings by the system; however, some variation with respect to lateral placement within the test lane was noted. The standard error calculated from all test runs is largely insignificant; this signifies consistent lane positioning from run to run for the evaluated roadway.

Within some areas along the roadway, the vehicle was offset towards the left side of the testing lane. This observation does not imply negative performance as the vehicle remained within the lane during the entirety of the test. However, this finding should be noted especially in the context of two-lane highways that are undivided from oncoming traffic.

### 6.2.2 Approaching a Disabled Vehicle

In both urban and rural driving environments, it is fairly common to encounter disabled vehicles along the side of the roadway. As the leading roadside assistance provider and traffic safety advocate, AAA is committed to raising awareness of the dangers associated with working at the roadside and promoting solutions to reduce resulting fatalities and injuries. Part of this commitment involves researching the implications of ADAS on roadside safety. Of particular interest is the performance of ADA systems as disabled vehicle(s) alongside or within the roadway are approached.

It is important to note the owner's manual for each test vehicle specifies the ADA system may not react when a lead vehicle is not completely within the travel lane.

The relevant excerpts are provided for reference:

**2019 BMW X7** – pg 236: “A vehicle driving in front of you is not detected until it is completely within the same lane as your vehicle.”

**2020 Kia Telluride** – pg 5-66: “Limitations of the sensors. The sensor may be limited when... the vehicle is stopped vertically.”

**2020 Subaru Outback** – pg 46 of EyeSight® supplementary owner’s manual: “The stereo camera may have difficulty detecting the following objects or conditions. Operate the brake pedal and take other actions as necessary... Vehicles at significantly different speeds (vehicles driving slowly, stopped or oncoming vehicles, etc.)”

It is acknowledged that this test evaluates system performance that may be outside of stated design capabilities. However, as these systems are specifically designed for highway use, it is nonetheless important to consider situations that may be reasonably expected during their use.

To simulate this situation, the DRI Soft Car 360® (herein referred to as the “target vehicle”) was parked approximately halfway off the right side of the testing lane previously described in [Section 4.2](#). In other words, the centerline of the vehicle was approximately located over the solid white line on the lateral side of the testing lane. The lateral placement of the target vehicle could be considered a best-case scenario in terms of detection opportunity with the exception of the target vehicle being placed directly in the center of the testing lane. In many cases when a disabled vehicle is partially within a roadway, it is common for only a small portion of the vehicle to obstruct the travel lane. A typical example would be a vehicle parked diagonally relative to the roadway with only the rear corner of the vehicle in the travel lane.



Figure 14: Lateral placement of DRI Soft Car 360® Image Source: AAA

The longitudinal placement was approximately halfway down the testing lane to allow sufficient space for steady-state speed to be reached a minimum of 1000 feet from the target vehicle. Three runs were performed for each test vehicle. For each run, the ADA system was engaged at 30 mph and allowed to reach steady-state speed as the test vehicle entered the testing lane. Hands were placed on the steering wheel and minimal steering input was provided if requested by the system. Since the driver

applied no acceleration input once the system was engaged, the actual test speed was determined by the system and may not actually reach 30 mph. As the test vehicle approached the target vehicle, no driver intervention was applied until contact was made with the target vehicle (if applicable). For each run, the following parameters were captured:

- Detection distance (ft)
- Detection time-to-collision (s)
- Separation distance at start of automatic braking (ft)
- Braking time-to-collision (s)
- Impact speed (mph)
- Separation Distance (ft)

Detection is considered to have occurred at the instant when a notification of an impending collision is provided by the system. Automatic braking is considered to have occurred once longitudinal deceleration exceeds 0.1 G.

#### 6.2.2.1 2019 BMW X7

	BMW X7					
	Detection Distance (ft)	Detection TTC (s)	Braking Distance (ft)	Braking TTC (s)	Impact Speed (mph)	Separation Distance (ft)
Run 1	N/A	N/A	N/A	N/A	28.9	0.00
Run 2	47.74	1.125	32.94	0.784	25.1	0.00
Run 3	121.65	2.860	96.68	2.304	0.0	4.66
Average	84.70	1.993	64.81	1.544	18.0	1.55
Standard Deviation	36.96	0.868	31.87	0.760	12.8	2.20

Figure 15: Run data for 2019 BMW X7 Image Source: AAA

Contact was made with the target vehicle for two out of three runs. However, some degree of braking mitigation was provided for two out of three runs. Specifically, one of these two runs resulted in a nominal speed reduction of 4.9 mph whereas a collision was avoided entirely on the second of these two runs. On average, the system mitigated an imminent collision by 12.0 mph relative to the nominal test speed of 30 mph. The high standard deviation pertaining to impact speed implies inconsistent performance when encountering the simulated disabled vehicle.

#### 6.2.2.2 2020 Kia Telluride

	Kia Telluride					
	Detection Distance (ft)	Detection TTC (s)	Braking Distance (ft)	Braking TTC (s)	Impact Speed (mph)	Separation Distance (ft)
Run 1	51.64	1.193	27.93	0.660	23.1	0.00
Run 2	43.80	1.017	15.81	0.372	27.3	0.00
Run 3	26.99	0.625	6.31	0.148	28.6	0.00
Average	40.81	0.945	16.68	0.393	26.3	0.00
Standard Deviation	10.28	0.237	8.85	0.210	2.3	0.00

Figure 16: Run data for 2020 Kia Telluride Image Source: AAA

Contact was made with the target vehicle for each of the three runs. However, some degree of braking mitigation was provided for each of the three runs. On average, the system mitigated an imminent collision by 3.7 mph relative to the nominal test speed of 30 mph. The relatively small standard

deviation pertaining to impact speed indicates consistent performance in terms of not significantly reacting to the simulated disabled vehicle.

#### 6.2.2.3 2020 Subaru Outlook

	Subaru Outlook					
	Detection Distance (ft)	Detection TTC (s)	Braking Distance (ft)	Braking TTC (s)	Impact Speed (mph)	Separation Distance (ft)
Run 1	97.30	2.244	85.65	1.999	0.0	2.64
Run 2	107.94	2.447	90.81	2.091	0.0	2.14
Run 3	58.28	1.322	45.11	1.034	14.4	0.00
Average	87.84	2.004	73.86	1.708	4.8	1.59
Standard Deviation	21.35	0.490	20.44	0.478	6.8	1.14

Figure 17: Run data for 2020 Subaru Outlook Image Source: AAA

Contact was made with the target vehicle for one out of three runs. Braking mitigation was provided for each of the three runs. On average, the system mitigated an imminent collision by 25.2 mph relative to the nominal test speed of 30 mph. For the run where impact occurred, a nominal speed reduction of 15.6 mph was observed. While this is a significant mitigation, the final impact speed is not trivial.

#### 6.2.2.4 Summary of Test Results




Figure 18: Average test vehicle detection distance and TTC Image Source: AAA

At 20 mph, each test vehicle provided notification of an imminent collision for a combined eight out of nine runs. Two out of three test vehicles completely avoided a collision with the target vehicle for at least one of three runs. However, for all nine test runs conducted in aggregate, a collision occurred 66 percent of the time.




Figure 19: Average test vehicle braking distance and TTC Image Source: AAA




Figure 20: Average test vehicle impact speed and separation distance Image Source: AAA

In a majority of cases, notification did not necessarily translate to collision avoidance. Specifically, while collision notification was provided for eight out of nine test runs in aggregate, a collision was avoided for only three out of nine runs. For collisions that occurred, the average impact and mitigation speed was 24.6 mph and 5.4 mph, respectively. It is also important to note for each test vehicle, performance varied significantly between the three test runs. Specifically, each test vehicle demonstrated some degree of inconsistency in terms of both detection and braking distance from run to run. Most importantly, each test vehicle impacted the target vehicle at least once. This illustrates that tested ADA systems cannot be trusted to consistently react to stopped vehicles either within or alongside the roadway. As such, drivers must maintain awareness of their surroundings and control of the vehicle at all times.

### 6.2.3 Traffic Jam Assistance

Previous AAA research found evaluated ADA systems performed well during naturalistic stop-and-go traffic. To build upon this work, stop-and-go traffic was simulated in order to evaluate system performance for various deceleration rates of a lead vehicle. The low-profile robotic vehicle (LPRV) was utilized as a dynamic platform for the DRI Soft Car 360® which acted as a surrogate lead vehicle.

The testing lane previously described in [Section 4.2](#) was utilized for testing. At the start of each test run, the test vehicle was maneuvered approximately ten feet behind the lead vehicle at which time the ADA system was enabled at a set speed of 30 mph. Approximately fifteen seconds after the ADA system was enabled, the lead vehicle began to accelerate with an average nominal acceleration of 0.11 G along the testing lane to a steady-state speed of 30 mph. The ADA system within each test vehicle was allowed to follow the lead vehicle with no driver applied acceleration. As a result, the final test vehicle speed may not be exactly 30 mph.

Hands were placed on the steering wheel and minimal steering input was applied if requested by the system. Five seconds after both vehicles reached steady-state speed, the lead vehicle initiated deceleration at the evaluated rates defined below. The average nominal deceleration was achieved within 0.5 seconds of initiation and was maintained until the lead vehicle came to a complete stop or test vehicle impact, whichever occurred first. Driver intervention was not provided at any point until the test vehicle came to a complete stop or the test vehicle made contact with the lead vehicle, whichever occurred first. For the test to be valid, the lead vehicle was required to remain within the test lane until coming to a complete stop.

Nominal deceleration rates of 0.30 G, 0.45 G and 0.60 G were evaluated in progressing order. Three runs for each deceleration rate were performed. Throughout each run, lead vehicle kinematics were recorded. Additionally, the following test vehicle parameters were calculated:

- Following distance
- Separation distance/time-to-collision at start of braking
- Speed differential at start of braking
- Average deceleration (averaged once longitudinal deceleration reached 0.1 G until the vehicle came to a complete stop)
- Maximum instantaneous deceleration

➤ Final separation distance

Characteristic test vehicle deceleration profiles associated with each lead vehicle deceleration rate are provided in following sections for additional discussion.

### 6.2.3.1 2019 BMW X7

	BMW X7						
	Following Distance (ft)	Braking Distance (ft)	Speed Differential at Start of Braking (mph)	Braking TTC (s)	Average Deceleration (G)	Max Deceleration (G)	Final Separation Distance (ft)
<b>0.30 G</b>							
Run 1	107.44	97.16	11.0	5.994	0.230	0.411	3.21
Run 2	92.78	82.61	15.0	5.510	0.282	0.455	2.51
Run 3	72.62	65.68	8.3	5.367	0.299	0.478	1.62
Average	90.95	81.82	11.4	5.624	0.270	0.448	2.45
Standard Deviation	14.27	12.86	2.8	0.268	0.029	0.028	0.65
<b>0.45 G</b>							
Run 1	97.72	82.14	15.3	3.656	0.328	0.464	3.08
Run 2	94.53	78.84	14.2	3.761	0.337	0.497	3.47
Run 3	88.23	73.40	14.7	3.388	0.409	0.940	1.44
Average	93.49	78.13	14.7	3.602	0.358	0.634	2.66
Standard Deviation	3.94	3.60	0.4	0.157	0.036	0.217	0.88
<b>0.60 G</b>							
Run 1	93.43	76.87	17.2	3.056	0.430	1.251	2.80
Run 2	92.42	73.41	18.1	2.748	0.485	1.317	4.82
Run 3	89.14	70.80	17.8	2.712	0.469	1.204	2.54
Average	91.66	73.69	17.7	2.839	0.461	1.257	3.39
Standard Deviation	1.83	2.49	0.4	0.154	0.023	0.046	1.02

Figure 21: Run data for 2019 BMW X7 Image Source: AAA

No contact was made with the lead vehicle during any test run, regardless of lead vehicle deceleration rate.




Figure 22: 2019 BMW X7 characteristic deceleration profile (0.30 G lead vehicle deceleration) Image Source: AAA




Figure 23: 2019 BMW X7 characteristic deceleration profile (0.45 G lead vehicle deceleration) Image Source: AAA




Figure 24: 2019 BMW X7 characteristic deceleration profile (0.60 G lead vehicle deceleration) Image Source: AAA

Figures 22-24 illustrate the deceleration profiles associated with each lead vehicle deceleration rate. At 0.30 G, the system decelerated smoothly as shown by the mostly linear rate of deceleration with a

maximum of roughly 0.45 G. At lead vehicle deceleration rates of 0.45 G and 0.60 G, the system exhibits a stepwise deceleration profile where the rate shortly plateaus at roughly 0.35 G before increasing sharply to approximately 0.50 G and 1.20 G for lead vehicle deceleration rates of 0.45 G and 0.60 G, respectively. These significant deceleration rates were largely maintained until the vehicle came to stop. As a result, stops were noticeably abrupt and non-linear relative to the lead vehicle deceleration rate of 0.30 G.

### 6.2.3.2 2020 Kia Telluride

	Kia Telluride						
	Following Distance (ft)	Braking Distance (ft)	Speed Differential at Start of Braking (mph)	Braking TTC (s)	Average Deceleration (G)	Max Deceleration (G)	Final Separation Distance (ft)
0.30 G							
Run 1	117.92	99.96	14.9	4.548	0.126	0.392	16.65
Run 2	109.06	94.44	14.3	4.510	0.130	0.378	7.45
Run 3	124.02	100.17	17.2	3.960	0.150	0.417	6.29
Average	117.00	98.19	15.5	4.339	0.135	0.396	10.13
Standard Deviation	6.14	2.65	1.2	0.269	0.010	0.016	4.63
0.45 G							
Run 1	99.92	86.96	14.2	4.185	0.146	0.533	11.82
Run 2	116.75	99.07	16.0	4.212	0.165	0.478	12.33
Run 3	117.80	102.56	18.1	3.855	0.206	0.508	13.51
Average	111.49	96.20	16.1	4.084	0.172	0.506	12.55
Standard Deviation	8.19	6.68	1.6	0.162	0.025	0.022	0.71
0.60 G							
Run 1	119.84	78.43	29.3	1.825	0.309	0.538	6.29
Run 2	120.71	88.52	25.5	2.360	0.314	0.493	8.14
Run 3	119.88	102.36	18.5	3.774	0.256	0.515	9.19
Average	120.14	89.77	24.4	2.653	0.293	0.515	7.87
Standard Deviation	0.40	9.81	4.5	0.822	0.026	0.018	1.20

Figure 25: Run data for 2020 Kia Telluride Image Source: AAA

No contact was made with the lead vehicle during any test run, regardless of lead vehicle deceleration rate.




Figure 26: 2020 Kia Telluride characteristic deceleration profile (0.30 G lead vehicle deceleration) Image Source: AAA




Figure 27: 2020 Kia Telluride characteristic deceleration profile (0.45 G lead vehicle deceleration) Image Source: AAA




Figure 28: 2020 Kia Telluride characteristic deceleration profile (0.60 G lead vehicle deceleration) Image Source: AAA

Figures 26-28 illustrate characteristic deceleration profiles associated with each lead vehicle deceleration rate. All deceleration profiles exhibit similar characteristics including a linearly increasing deceleration rate to a plateau between 0.35 G to 0.40 G. After the rate plateaus, the deceleration rate gradually decreases as the vehicle comes to a stop. At 0.30 G, the vehicle crept forward momentarily before coming to a complete stop. Regardless of lead vehicle deceleration rate, stops were noticeably smooth relative to other test vehicles.

### 6.2.3.3 2020 Subaru Outback

	Subaru Outback						
	Following Distance (ft)	Braking Distance (ft)	Speed Differential at Start of Braking (mph)	Braking TTC (s)	Average Deceleration (G)	Max Deceleration (G)	Final Separation Distance (ft)
<b>0.30 G</b>							
Run 1	78.53	71.73	7.7	6.373	0.204	0.425	9.50
Run 2	85.34	76.02	9.0	5.755	0.178	0.473	7.48
Run 3	87.13	79.16	8.6	6.296	0.171	0.422	8.96
Average	83.67	75.64	8.4	6.141	0.184	0.440	8.65
Standard Deviation	3.70	3.05	0.5	0.275	0.014	0.023	0.85
<b>0.45 G</b>							
Run 1	89.95	78.80	12.3	4.344	0.231	0.479	6.13
Run 2	85.96	73.97	12.5	4.043	0.327	0.499	3.04
Run 3	87.03	75.38	12.4	4.128	0.323	0.508	7.72
Average	87.65	76.05	12.4	4.172	0.294	0.495	5.63
Standard Deviation	1.69	2.03	0.1	0.127	0.044	0.012	1.94
<b>0.60 G</b>							
Run 1	87.41	70.91	17.0	2.852	0.482	1.010	2.62
Run 2	85.39	70.59	15.9	3.017	0.428	0.987	2.35
Run 3	83.99	68.12	16.4	2.824	0.440	1.056	2.09
Average	85.60	69.87	16.4	2.898	0.450	1.018	2.35
Standard Deviation	1.40	1.25	0.4	0.085	0.023	0.029	0.22

Figure 29: Run data for 2020 Subaru Outback Image Source: AAA

No contact was made with the lead vehicle during any test run, regardless of lead vehicle deceleration rate.




Figure 30: 2020 Subaru Outlook characteristic deceleration profile (0.30 G lead vehicle deceleration) Image Source: AAA




Figure 31: 2020 Subaru Outlook characteristic deceleration profile (0.45 G lead vehicle deceleration) Image Source: AAA




Figure 32: 2020 Subaru Outlook characteristic deceleration profile (0.60 G lead vehicle deceleration) Image Source: AAA

Figures 30-32 illustrate characteristic deceleration profiles associated with each lead vehicle deceleration rate. At 0.30 G and 0.45 G, the system decelerated with a linearly increasing rate and plateaued approximately between 0.40 G to 0.45 G before linearly decreasing until the vehicle was almost stopped. At this point, the vehicle crept forward slightly before coming to a complete stop. At 0.60 G, the system exhibited a multi stepwise deceleration profile with brief plateaus at 0.40 G and 0.65 G before increasing to a maximum at approximately 1.00 G. This maximum rate was maintained until the vehicle came to a stop, resulting in a noticeably abrupt stop.

#### 6.2.3.4 Summary of Test Results




Figure 33: Average test vehicle following distance Image Source: AAA

Figure 33 illustrates for each test vehicle, differences in following distance with respect to lead vehicle deceleration were not significant. This is an expected result; the only parameter that is anticipated to influence following distance is vehicle speed. For all runs, the test vehicle nominal speed was kept constant at 30 mph.




Figure 34: Average separation distance at start of braking Image Source: AAA




Figure 35: Average test vehicle TTC at start of braking Image Source: AAA

For two out of three test vehicles, the average separation distance at the start of braking slightly decreased as the lead vehicle deceleration rate increased. As a result of decreased separation distance

and increased lead vehicle deceleration, the time-to-collision consequently decreased as the lead vehicle deceleration rate increased.




Figure 36: Average test vehicle deceleration Image Source: AAA




Figure 37: Averaged maximum instantaneous test vehicle deceleration Image Source: AAA

For each test vehicle, the average deceleration rate increased as the lead vehicle deceleration rate increased as shown in Figure 36. Additionally, the maximum instantaneous deceleration increased along with lead vehicle deceleration as shown in Figure 37. Two out of three test vehicles exhibited instantaneous maximum decelerations exceeding 1.0 G. This illustrates evaluated systems are capable of applying significant braking input in response to lead vehicle deceleration. However, abrupt stops with high deceleration rates may introduce the possibility of rear-end collisions because following vehicles will have limited time to react.




Figure 38: Average test vehicle/lead vehicle separation distance Image Source: AAA

The final separation distance did not vary consistently among test vehicles with respect to lead vehicle deceleration rate as shown in Figure 38. Specifically, the final separation distance slightly increased with increasing lead vehicle deceleration for the BMW X7 whereas the opposite is true for the Subaru Outback. However, the most significant finding is all test vehicles avoided contact with the lead vehicle for all test runs conducted regardless of tested lead vehicle deceleration rate.

### 6.3 Overall Summary of Closed-Course Performance

In the context of controlled closed-course evaluations, each ADA system generally performed according to expectations derived from the owner's manual of each test vehicle.

Each evaluated ADA system was able to maintain consistent lane positioning from run to run and remain within the lane markers throughout the entirety of the testing lane. For each vehicle, some biases towards either the right or left of the lane center were observed. Additionally, each vehicle exhibited some variation in lateral lane placement as the vehicle traversed the testing lane.



When encountering a simulated disabled vehicle placed halfway within the testing lane in the lateral direction, all test vehicles made contact for at least one out of three test runs. In aggregate, a collision occurred 66 percent of the time. For collisions that occurred, the average impact and mitigation speed was 24.6 mph and 5.4 mph, respectively.

In a simulated stop-and-go scenario, each evaluated ADA system made no contact with the lead vehicle during any test run, for lead vehicle deceleration rates up to and including 0.60G. This indicates good longitudinal performance in the context of deceleration rates typically observed in the naturalistic environment.

While systems generally performed according to expectations, closed-course evaluation illustrated all systems are incapable of consistently reacting to a scenario of a disabled vehicle partially within the roadway. All available ADA systems are not capable of sustained operation without constant driver supervision. Drivers must be prepared to intervene anytime ADA systems are engaged.

## 7 Inquiry 2: How do vehicles equipped with ADA systems perform during naturalistic highway driving?

### 7.1 Objective

Evaluate test vehicles in naturalistic highway environments to determine how ADA systems influence the driving experience.

### 7.2 Methodology

Each test vehicle was evaluated on U.S Highway 101 and Interstate 5 between the greater Los Angeles and San Francisco metropolitan areas. Specifically, U.S Highway 101 was traveled from Los Angeles to San Francisco and Interstate 5 was traveled from San Francisco to Los Angeles. Additionally, a section of Interstate 680 was traversed to arrive at the testing destination from Highway 101; this interstate along with Interstate 580 was also utilized to access Interstate 5 from the San Francisco area. These highways were utilized for evaluation because both routes are representative of the design domain for tested ADA systems. Generally, roadways were well maintained with well-defined lane markers and consistent lane width. However, utilized roadways also contained sections of road work resulting in lane closures, missing or inconsistent lane markers and/or uneven pavement. In particular, significant wear and faded lane markers were observed on sections of Interstate 5.

Throughout the route, U.S Highway 101 consisted of a four-lane divided highway with varying speed limits between 35 mph through populated areas up to 65 mph in rural areas. Additionally, some sections were significantly curved both along the coast and through hilly inland areas. Approximately 430 miles were traversed on this route.

Interstate 5 is a limited access expressway with a speed limit of 70 mph throughout a majority of the route. The majority of Interstate 5 utilized for evaluation consisted of long, straight sections with unrestricted sightlines outside urban areas. Approximately 370 miles were traversed on this route.



To ensure conditions were as consistent as possible for each test vehicle, all vehicles were instrumented and driven along the route simultaneously with ADA systems engaged. To prevent ADA systems from influencing each other, a separation distance of several miles was maintained between all test vehicles. A total of six test drivers were utilized for naturalistic evaluations; both routes were sectioned into approximately equal sections in which drivers would switch vehicles. Drivers spent an approximately equal time behind the wheel of each test vehicle to minimize driver variation between evaluated ADA systems. Immediately after the conclusion of each segment, drivers filled out a subjective feedback form recording their impressions of the ADA system. Specifically, questions relating to the following were included:

- Forward Collision Warning timing
- Lane Departure Warning timing
- Comfort of Adaptive Cruise Control braking and acceleration
- Lane keeping corrections
- Awareness of system engagement/disengagement
- Understanding of warnings
- Tendency of lane placement
- Ease and enjoyment of ADA system use
- Overall trust of ADA system
- Additional comments

Super Cruise™ within the 2019 Cadillac CT6 is technically considered a SAE J3016 Level 2 system. However, it is inherently distinct from other evaluated ADA systems due to its restriction to LIDAR mapped highways and interstates. Additionally, the system specifically allows hands free operation during engagement.

For every significant event related to system operation, a bookmark was placed within the data file to mark the event for post-processing. Examples of significant events include but are not limited to:

- Lane departures
- Erratic lane positioning
- Inadequate braking
- Unexpected speed fluctuations
- Inappropriate following distance

Instances of unexpected system disengagement, failure to engage/re-engage and other unexpected and/or undesired behavior were also marked for post-processing. For each marked event, roadway, GPS location, event type, vehicle speed, longitudinal/lateral acceleration and event comments were recorded. For each vehicle, a table with this information is provided in the Appendix.

Despite best efforts to ensure consistent environmental conditions and driver profiles for each test vehicle, strict quantitative comparison of naturalistic performance between evaluated ADA systems is not possible within the scope of this work for two primary reasons. Driver risk tolerance and event sensitivity is a factor during naturalistic evaluations; specifically, each test driver varied in terms of how

much they would allow the system to perform poorly before intervening. For example, one driver may allow a vehicle an opportunity to correct erratic lane positioning whereas another driver might immediately intervene. Driver risk tolerance is also likely to vary for the same individual depending on the specific situation. In this context, erratic lane positioning describes weaving or “ping-ponging” within the travel lane or lateral lane positioning significantly off-center.

Additionally, drivers varied in terms of what he/she considered a noteworthy event. Regardless of drivers spending an approximately equal time in each test vehicle, differences in traffic, road condition, lighting, sun angle, etc. along the route will invariably present differing environmental conditions as each driver pilots each test vehicle.

### 7.3 Results and Observations

For each vehicle, subjective ratings are provided in the Appendix.

#### 7.3.1 2019 BMW X7

Event Occurrences	
Lane Departure	13
Erratic Lane Position	56
Failure to Slow/Stop	1
Other	15
<b>Total</b>	<b>85</b>

Figure 39: Number of events by type for the 2019 BMW X7 Image Source: AAA




Figure 40: Percent distribution of events by type for the 2019 BMW X7 Image Source: AAA

Figures 39 and 40 illustrate the total number and distribution of each event type observed during naturalistic evaluation. In total, approximately 800 miles were traversed; this translates into roughly one event every 9 miles for the roadways traveled.

Sixty-six percent of events were classified as erratic lane positioning and an additional 15 percent of events were classified as lane departures. In total, 81 percent of noted events pertained to the lane keeping functionality of the BMW's Active Driving Assistant Professional system. Despite this finding, some test drivers noted good general performance in slight and moderate curves. Most test drivers also felt the system performed well during periods of light highway traffic and stop-and-go traffic.

All test drivers commented the system would require frequent steering input; this characteristic is notable because of its potential to limit driver distraction. However, the system frequently requested hands to be placed on the steering wheel when the driver was already holding the wheel. To keep the system engaged, drivers were repeatedly required to provide unnecessary steering input. This occurred with enough frequency to significantly detract from the driving experience in some cases.

Figure 41 tabulates some general observations of the Active Driving Assistant Professional system as noted by test drivers. In aggregate, all test drivers noted relatively few complete lane departure events and good performance within curved sections of roadway. Additionally, the adaptive cruise component was noted to accelerate in a responsive manner within heavy traffic; this can be beneficial because of the tendency of other drivers to "cut off" vehicles that accelerate slowly relative to traffic flow.

System Observations
Few lane departure events
Lane centering component very good with curvy roads
System accelerates well especially in traffic with system on closest setting
Too sensitive with steering requests for hands to be on wheel
Sometimes system disengages for no reason, throwing vehicle out of lane, there was no lane keep assist from vehicle
ACC system is sensitive, not a natural feeling
System fought user with steering wheel, stiff steering due to lane centering causing resistance
Vehicle maintains center but with lots of hunting in the lane, turns off when turn signal goes on
System would repeatedly ask for hands on steering wheel when they already were, to the point where it would significantly detract from the experience
Overall, very good with lane centering with only a few exceptions on curved roadways.
Clear "head-up display" with clear system "ON" indicators
Head-up display was invisible most of drive (sun to left and polarized sunglasses)

Figure 41: Common observations for the 2019 BMW X7 Image Source: AAA

In addition to the sensitivity of the system in terms of requested steering input, some test drivers noted instances of unexpected system disengagement. These disengagements sometimes resulted in a lane departure with no auxiliary lane keeping assistance. Overall, test drivers were aware of system status with unambiguous colored icons.

### 7.3.2 2019 Cadillac CT6

Event Occurrences	
Lane Departure	2
Erratic Lane Position	6
Failure to Slow/Stop	0
Other	44
<b>Total</b>	<b>52</b>

Figure 42: Number of events by type for the 2019 Cadillac CT6 Image Source: AAA




Figure 43: Percent distribution of events by type for the 2019 Cadillac CT6 Image Source: AAA

Figures 42 and 43 illustrate the total number and distribution of each event type observed during naturalistic evaluation. In total, approximately 800 miles were traversed; this translates into roughly one event every 15 miles for the roadways traveled.

Eighty-five percent of events were classified as “other”; 37 out of 44 of these events were either unexpected or erroneous system disengagements. Some disengagements occurred at critical times such as in the middle of a curve with rapidly slowing traffic ahead. While it was easily apparent disengagement occurred, test drivers were sometimes taken by surprise and were required to retake full control in the middle of critical situations with little to no advance notice. Additionally, a significant number of disengagements were noted during which driver inattention was incorrectly detected. This occurred with enough frequency to noticeably detract from the driving experience.

To further understand the nature of disengagements of the Super Cruise™ system, a different 2020 Cadillac CT6 with Super Cruise™ was procured and driven approximately 1,500 miles on Florida

interstates with the system engaged. To maintain consistency in terms of event counting relative to other test vehicles, events noted during this evaluation were not included in Figures 42 and 43.

During this subsequent evaluation, it was noted that system disengagements upon approaching work zones or areas where no mapping information was available were characteristically abrupt. For this particular scenario, the system did not entirely disengage but quickly began slowing the vehicle down while simultaneously vibrating the driver's seat and muting the audio system with verbal instructions to retake control.

This process of system disengagement would benefit by notifying the driver that the system is approaching an area where a complete handover of vehicle control is necessary. Based on current understanding of human reengagement time and variations due to cognitive load, degree of disengagement, age, driver condition (i.e. drowsiness, impairment, illness) and environmental factors, a minimum of twenty seconds between initial notification and required driver takeover is ideal [5]. An additional factor behind this recommendation relates to the unique characteristic of the Super Cruise™ system to allow hands-free driving.

Figure 44 tabulates some general observations of the Super Cruise™ system as noted by test drivers. In aggregate, all test drivers felt the system performed well during periods of light highway traffic. This observation in combination with hands-free operation enhanced the driving experience for all test drivers. In general, all drivers noted the system would not allow sustained inattention; the status of the system was also unambiguous due to the light bar on the steering wheel.

System Observations
<p>No lane departure events, lane centering works well, good job on light interstate traffic when system is engaged.</p> <p>Hands-free operation enhances drive.</p> <p>Overall smooth operation and good operation on open highway.</p> <p>System forces you to look at the road.</p> <p>Repetitive visual icons.</p> <p>System disengaged repeatedly when conditions were normal and during curvy roads.</p> <p>Following distances were too large.</p> <p>Over confidence could create disengaged driver.</p> <p>Very busy with too many indicators. Noticably distracting.</p> <p>System disengaged during critical situations with little warning.</p> <p>System would disengage repeatedly because it was difficult for system to recognize face especially with sunglasses.</p> <p>System would sometimes disengage even when I was looking at the road. This happened multiple times and detracted from the experience.</p> <p>System feels unnatural through curves.</p> <p>Super Cruise not available for a good portion of the drive - possibly due to sun angle.</p> <p>System will lock out if camera is blocked.</p>

Figure 44: Common observations for the 2019 Cadillac CT6 Image Source: AAA

Overall, the system was less prone to erratic lane positioning and lane departures than other evaluated systems. Additionally, no events pertaining to a failure to slow or stop were noted. However, the primary disadvantage of the system noted by all test drivers pertains to the sudden and repeated occurrence of erroneous and/or critical disengagements. This significantly detracted from the driving experience and presented a hazardous condition in some situations.

### 7.3.3 2019 Ford Edge

Event Occurrences	
Lane Departure	65
Erratic Lane Position	86
Failure to Slow/Stop	1
Other	20
<b>Total</b>	<b>172</b>

Figure 45: Number of events by type for the 2019 Ford Edge Image Source: AAA




Figure 46: Percent distribution of events by type for the 2019 Ford Edge Image Source: AAA

Figures 45 and 46 illustrate the total number and distribution of each event type observed during naturalistic evaluation. In total, approximately 800 miles were traversed; this translates into roughly one event every 5 miles for the roadways traveled.

Fifty percent of events were classified as erratic lane positioning and an additional 38 percent of events were classified as lane departures. In total, 88 percent of noted events pertained to the lane keeping functionality of the Ford Co-Pilot 360™ system. Both the percent distribution of lane keeping related events and the frequency of occurrence relative to other test vehicles caused general distrust of the system by all test drivers. As a result, the majority of test drivers felt the lane keeping functionality did not enhance the driving experience in most environments; in some cases, test drivers felt the functionality was instead a detriment.

Figure 47 tabulates some general observations of the Ford Co-Pilot 360™ system as noted by test drivers. In aggregate, the system was observed to perform well in terms of longitudinal control (adaptive cruise functionality). However, it was noted the system frequently favored the left side of the

lane and had trouble with certain lane marker types. Additionally, it was noted the system either would not engage or frequently disengage during periods of low vertical sun angle.

System Observations
Adaptive cruise system performed well (acceleration and braking).
Unobtrusive and helpful.
System did not engage for significant part of the drive or would turn off.
Vehicle came too close to other vehicle and guardrails.
Poor system performance (e.g. would not hold lane or would keep vehicle towards left side of lane).
Over correction and late reaction by system in response to road conditions (e.g. late ACC deceleration).
User correction needed when vehicle departed lane.
System was significantly affected by sun angle.
Lane centering mostly kept vehicle towards left side of lane.
Multiple issues with solid lane marker lines (both right and left), system would frequently cross over.
System did not instill trust within driver.
System would randomly steer.


Figure 47: Common observations for the 2019 Ford Edge Image Source: AAA

In general, all test drivers noted good performance of the adaptive cruise functionality within the Ford Co-Pilot 360™ system. This performance was noted to enhance the driving experience within stop-and-go highway environments. Additionally, unexpected system disengagements did not occur with enough frequency to be problematic. However, the general lack of performance relative to lane keeping functionality significantly diminished the value of the system as a highway driving aid and sometimes added to the overall workload for the driver.

#### 7.3.4 2020 Kia Telluride

Event Occurrences	
Lane Departure	58
Erratic Lane Position	28
Failure to Slow/Stop	5
Other	18
<b>Total</b>	<b>109</b>

Figure 48: Number of events by type for the 2020 Kia Telluride Image Source: AAA



**Figure 49: Percent distribution of events by type for the 2020 Kia Telluride** Image Source: AAA

Figures 48 and 49 illustrate the total number and distribution of each event type observed during naturalistic evaluation. In total, approximately 800 miles were traversed; this translates into roughly one event every 7 miles for the roadways traveled.

Fifty-three percent of events were classified as lane departures with an additional 26 percent of events classified as erratic lane positioning. In total, 79 percent of noted events pertained to the lane keeping functionality of the Highway Driving Assist system. Additionally, all test drivers noted the system would allow a significant amount of time to elapse before requesting steering input. This represents a potentially hazardous combination; drivers may get lulled into a false sense of security during which a lane keeping event may occur unexpectedly.

Despite the distribution of lane keeping events, most test drivers felt the system complemented the driving experience during light freeway traffic and stop-and-go traffic.

Figure 50 tabulates some general observations of the Highway Driving Assist system as noted by test drivers. In aggregate, the system was observed to perform well in terms of both lateral and longitudinal control (adaptive cruise and lane-keeping functionality). However, it was noted the adaptive cruise functionality was prone to delayed acceleration and deceleration in response to the driving environment.

System Observations
Good lane centering and adaptive cruise performance.
Audio/Visual alerts are clear and intuitive.
Dash symbols hard to read and understand.
System disengagement easy to miss.
Slow responses from adaptive cruise system (acceleration/deceleration).
System allows too much time (~2min) without hands on steering wheel.
False sense of security.

Figure 50: Common observations for the 2020 Kia Telluride Image Source: AAA

All test drivers shared a general consensus that changes in system status (i.e. disengagements) were sometimes easy to miss due to inconspicuous icons within the instrument cluster. When combined with the finding that the system would sometimes allow approximately two minutes to elapse without requesting steering input, it is possible drivers could be unaware of system disengagements for an extended period.

### 7.3.5 2020 Subaru Outback

Event Occurrences	
Lane Departure	35
Erratic Lane Position	30
Failure to Slow/Stop	0
Other	38
<b>Total</b>	<b>103</b>

Figure 51: Number of events by type for the 2020 Subaru Outback Image Source: AAA




Figure 52: Percent distribution of events by type for the 2020 Subaru Outback Image Source: AAA

Figures 51 and 52 illustrate the total number and distribution of each event type observed during naturalistic evaluation. In total, approximately 800 miles were traversed; this translates into roughly one event every 8 miles for the roadways traveled.

Thirty-four percent of noted events were classified as lane departures and an additional 29 percent of events related to erratic lane positioning. In total, 63 percent of events pertained to the lane-keeping functionality of the EyeSight® system. The remaining 37 percent of noted events were due to unanticipated system disengagement or a failure to engage.

All test drivers noted the inability of the system to consistently negotiate moderate curves; the system would either disengage upon approaching the curve or depart the lane before immediately disengaging. Interestingly, the system would frequently issue a lane departure warning while disengaging simultaneously. This implies while the system can recognize curved lane markers, the system is limited in terms of maximum steering input.

Figure 53 tabulates some general observations of the EyeSight® system as noted by test drivers. In aggregate, test drivers felt the EyeSight® system enhanced the driving experience in non-demanding environments such as straight roadways with light traffic. Additionally, strong performance of the adaptive cruise functionality was noted by all test drivers; no events pertaining to longitudinal control were noted during naturalistic evaluation. In particular, the system provided unambiguous confirmation that the lead vehicle was detected.

Primary disadvantages relate to the general inability of the system to negotiate moderate curves and frequent disengagement within this environment and within heavy traffic.

System Observations
<p>Very seamless in non-challenging scenarios, worked relatively well in light traffic and gradual corners.</p> <p>Easy to engage.</p> <p>Adaptive Cruise worked well with good acceleration when re-engaging system.</p> <p>Alerts clear.</p> <p>Did not have to fight system for control.</p> <p>Picks up vehicles entering/exiting lane very well.</p> <p>System too sensitive in terms of asking/requesting hands on wheel when hands were already on wheel.</p> <p>Incapable of handling curvy roadways.</p> <p>Some beeps and lights were ambiguous and too frequent.</p> <p>System repeatedly disengaged in heavy traffic.</p> <p>Noticable "ping-ponging" in curves.</p> <p>Difficult to engage, hard to get to engage and stay engaged.</p> <p>System was not capable in moderate curves and would either disengage or depart the lane.</p> <p>Not very capable on curved roadways.</p> <p>Long stretches where system did not engage</p> <p>Lane departure visual is distracting in critical situations.</p>

Figure 53: Common observations for the 2020 Subaru Outback Image Source: AAA

## 7.4 Overall Summary of Naturalistic Evaluation

In total, approximately 4,000 miles were traversed among five test vehicles. During naturalistic evaluation, 521 events were noted; this translates to approximately one event every 8 miles. In aggregate, 73 percent of noted events related to the lane-keeping functionality of the ADA system. The majority of events classified as “other” related to system disengagement or failure to engage. This finding is similar to earlier work in 2018 which observed 88 percent of events in the naturalistic setting

related to the lane-keeping functionality of evaluated systems. For detailed methodology, refer to the research report on the [AAA NewsRoom](#).

Event Occurrences	
Lane Departure	173
Erratic Lane Position	206
Failure to Slow/Stop	7
Other	135
<b>Total</b>	<b>521</b>

Figure 54: Number of events by type for all test vehicles Image Source: AAA




Figure 55: Percent distribution of events by type for all test vehicles Image Source: AAA

Based on findings from earlier work, naturalistic evaluations exclusively focused on the highway environment. In general, all test drivers noted the adaptive cruise functionality of evaluated systems performed well, sometimes exceeding expectations. However, each test driver noted some degree of flawed performance during each drive of every test vehicle in terms of lane-keeping functionality. The specific nature of lane-keeping events were varied; common events are listed below:

- Abrupt disengagements (sometimes during critical situations)
- Failure to engage
- Erroneous disengagements in terms of perceived inattention
- “Ping-ponging” within the lane
- Becoming uncomfortably close to other vehicles or guardrails in the lateral direction

- Complete lane departures within:
  - Curves
  - Pavement transitions
  - Upon encountering exit ramps/on-ramps

Based on the lane-keeping ability of each test vehicle, each driver felt all evaluated ADA systems enhanced the driving experience (to varying extents) only in the context of stop-and-go traffic or on simple, well-maintained highways with little traffic. However, due to the frequency and unpredictability of lane-keeping events, all test drivers expressed some level of distrust for each system. Additionally, all test drivers reached a general consensus that combining adaptive-cruise and lane-keeping functionalities in a single system did not consistently enhance the driving experience. In contrast, some test drivers reported evaluated ADA systems could sometimes increase perceived driver workload because constant monitoring and intervention in many cases was required.

## 8 Overall Conclusions

Research conducted by the AAA Foundation for Traffic Safety evaluated the potential impacts of Level 2 automation equipped vehicles on driving behavior [6]. A general conclusion of the work originated from a 12-month field evaluation of 50 participant-owned vehicles. Since “test” vehicles were owned and operated prior to the study, it can be assumed participants already had some degree of familiarity with the system. As a result, this data may be indicative of long-term adaptation and behavior effects. In general, this evaluation showed a greater impact on various driver behavioral measures when ADA systems were active compared to when these systems were not active but available. Eye-glance metrics indicated drivers had their eyes off-road and on non-driving-related tasks more frequently and for longer durations when ADA systems were active compared to any other system status.

This observation is troubling when combined with findings of this work in both closed-course and naturalistic environments. In both environments, clear examples of critical performance demerits that may result in a serious collision were observed.

In the closed-course environment, all test vehicles evaluated in this context impacted a simulated disabled vehicle at least once when evaluated at 30 mph. Among test vehicles, the highest average detection/notification TTC was approximately two seconds. In a real-world situation where a driver is disengaged from the driving task for a significant duration, he/she may be unaware of an upcoming critical situation. In this scenario, it is unlikely a notification provided two seconds prior to an impending collision will provide enough time for the driver to avoid impact if the system does not adequately intervene.

During naturalistic evaluations, an adverse event was observed on average, once every 8 miles. As highway speeds typically exceed 60 mph, an unexpected lane departure that occurs in combination with a disengaged driver is potentially hazardous for two main reasons. First, a driver simply may not have time to avoid a potential collision either with a vehicle alongside or a stationary object on the side of the roadway. Additionally, a driver may be taken by surprise when regaining situational awareness and consequently overcorrect, potentially resulting in loss of vehicle control.



Nothing contained within this report is intended to directly imply evaluated ADA systems are inherently unsafe. In totality, this work is intended to illustrate potential system inadequacies in the context of scenarios realistically encountered in a naturalistic environment. Additionally, all test drivers expressed some degree of distrust in each evaluated system and questioned the overall usefulness of integrating adaptive cruise and lane-keeping functionalities.

This work emphasizes the need for additional refinement of ADAS systems as a whole and for the automotive industry to collaboratively consider how current iterations of ADAS technology align with driver perception and behavior. Multiple facets relating to system programming, edge-case scenario design considerations, human/machine interactions and driver training should be considered in order to most effectively design and promote ADAS systems that provide the most benefit to the driving public.

## 9 Key Findings

1. In general, evaluated ADA systems performed according to expectations derived from the owner's manuals during closed-course evaluations.
  - a. On fresh pavement with well-defined lane markers, all systems consistently traversed the testing lane with some lateral offsets relative to the lane center.
  - b. In aggregate, evaluated ADA systems made contact with a simulated disabled vehicle 66% of the time.
  - c. For a simulated stop-and-go scenario, none of the evaluated ADA systems made contact with a lead vehicle for all tested deceleration rates.
2. Test drivers reached a consensus that over approximately 4,000 miles of total driving distance, combining longitudinal and lateral control into a single system did not significantly enhance the driving experience for the majority of encountered scenarios. On roadways utilized for evaluation:
  - a. Lane-keeping events accounted for 73% of noted events.
    - i. The Super Cruise™ system exhibited significantly less lane-keeping events in terms of distribution and frequency relative to other evaluated systems. However, test drivers expressed concern about sudden system disengagements with little warning.
  - b. A total of 521 events were noted among all evaluated ADA systems. On average, this resulted in a noteworthy event approximately every eight miles.

## 10 Summary Recommendations

1. **Currently available ADA systems are not capable of sustained vehicle operation without constant driver supervision; it is imperative the driver maintain situational awareness at all times.**



2. The adaptive cruise component of all evaluated ADA systems performed well during naturalistic driving as evidenced by the low frequency of events related to this functionality. Improved tuning of the lane keeping component may bring a significant performance improvement to ADA systems.
3. For all evaluated vehicles, test drivers sometimes found that ADA system status was unclear and/or were taken by surprise with sudden/unexpected disengagements. Additional consideration of the human/machine interface will bring improved driver confidence pertaining to the use of ADA systems.



## 11 Appendix

### 11.1 2019 BMW X7

Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
Hwy 101	34°4.610568 N	118°16.781400 W	Erratic Lane Positioning	40	-0.06	0.05	Riding on the right side of the lane
Hwy 101	34°9.148620 N	118°22.516530 W	Erratic Lane Positioning	57	0.04	0.17	Steering is bouncing back and forth and ping ponging on S turn
Hwy 101	34°9.867738 N	118°28.382862 W	Erratic Lane Positioning	47	0.00	0.18	Vehicle having a hard time centering itself on a curve
Hwy 101	34°14.516736 N	119°11.275098 W	Other	68	0.04	0.03	
Hwy 101	34°22.777446 N	119°28.874832 W	Other	56	0.04	0.02	
Hwy 101	34°22.823226 N	119°28.901556 W	Erratic Lane Positioning	57	0.03	0.06	Lane marker disappeared due to exit, vehicle bounced back and forth a bit but regained the lane and recovered
Hwy 101	34°23.832132 N	119°30.699486 W	Erratic Lane Positioning	51	0.15	0.10	Vehicle got too close to adjacent lane on a slight curve, system disengaged
Hwy 101	34°24.991110 N	119°33.796122 W	Erratic Lane Positioning	70	-0.05	-0.05	Vehicle went outside of lane
Hwy 101	34°25.257144 N	119°37.431792 W	Other	62	0.03	-0.08	System disengagement without obvious cause
Hwy 101	34°26.388012 N	119°56.303202 W	Erratic Lane Positioning	68	0.00	-0.11	
Hwy 101	34°27.642114 N	120°0.085536 W	Erratic Lane Positioning	68	0.00	0.04	
Hwy 101	34°27.679944 N	120°0.317604 W	Erratic Lane Positioning	68	-0.07	-0.02	
Hwy 101	34°27.821688 N	120°1.672410 W	Erratic Lane Positioning	68	0.03	-0.02	
Hwy 101	34°27.786510 N	120°3.639246 W	Lane Departure	68	-0.02	-0.01	Right side
Hwy 101	34°27.831306 N	120°3.761190 W	Lane Departure	68	-0.02	-0.16	Left side
Hwy 101	34°28.388604 N	120°7.750734 W	Erratic Lane Positioning	69	0.02	0.00	
Hwy 101	34°28.980174 N	120°13.820598 W	Lane Departure	62	0.00	-0.31	Left side
Hwy 101	34°29.095566 N	120°13.762980 W	Lane Departure	62	-0.05	-0.28	
Hwy 101	34°29.127246 N	120°13.726812 W	Erratic Lane Positioning	62	-0.01	-0.02	
Hwy 101	34°29.366772 N	120°13.557408 W	Failure to Slow/Stop	44	0.05	0.21	Truck with trailer crossed into lane
Hwy 101	34°35.430288 N	120°11.551818 W	Erratic Lane Positioning	67	-0.11	-0.03	
Hwy 101	34°35.572218 N	120°11.648142 W	Erratic Lane Positioning	61	-0.04	-0.14	
Hwy 101	34°44.317536 N	120°15.881916 W	Erratic Lane Positioning	66	-0.06	-0.15	
Hwy 101	34°53.400156 N	120°25.018092 W	Lane Departure	70	-0.03	-0.12	Right side
Hwy 101	35°8.627430 N	120°38.467278 W	Other	68	-0.05	-0.11	System disengagement
Hwy 101	35°17.506974 N	120°39.147234 W	Erratic Lane Positioning	63	-0.06	-0.16	Vehicle hugging right lane marker
Hwy 101	35°18.976488 N	120°37.288914 W	Lane Departure	69	-0.01	0.07	Lane Departure/System Disengagement
Hwy 101	35°32.930652 N	120°42.946362 W	Erratic Lane Positioning	67	0.00	-0.22	Hugging right side of the road/Lane Departure
Hwy 101	35°38.031042 N	120°41.147106 W	Erratic Lane Positioning	72	-0.01	-0.16	"Ping-ponging" within lane
Hwy 101	35°44.844918 N	120°42.020016 W	Other	56	-0.04	-0.08	System disengagement, lane might be too wide
Hwy 101	35°45.623652 N	120°41.922768 W	Other	63	-0.01	0.08	Right lane may be too wide for system to engage
Hwy 101	36°3.176220 N	120°58.151154 W	Other	73	-0.07	0.04	
Hwy 101	36°3.734796 N	120°58.815528 W	Other	73	-0.04	-0.06	
Hwy 101	36°12.046650 N	121°6.604884 W	Erratic Lane Positioning	54	0.00	0.03	
Hwy 101	36°19.695606 N	121°14.541420 W	Other	67	0.00	-0.01	
Hwy 101	36°30.658302 N	121°26.180406 W	Lane Departure	65	0.06	-0.04	
Hwy 101	36°54.234828 N	121°33.395556 W	Other	76	0.08	-0.01	System disengagement
Hwy 101	37°11.779122 N	121°42.052890 W	Erratic Lane Positioning	71	-0.02	-0.02	"Ping-ponging" within lane
Hwy 101	37°17.242194 N	121°48.563604 W	Erratic Lane Positioning	68	-0.03	-0.02	"Ping-ponging" within lane
Hwy 101	37°20.248242 N	121°50.921694 W	Lane Departure	66	-0.03	0.04	Lane departure right side
I-680	37°42.296796 N	121°55.481814 W	Erratic Lane Positioning	64	-0.02	0.00	Hugging left side of lane in merge area
I-680	37°53.262930 N	122°3.412302 W	Lane Departure	68	0.03	0.03	
I-680	37°53.078208 N	122°3.256758 W	Lane Departure	68	0.03	0.06	
I-680	37°52.915062 N	122°3.075024 W	Erratic Lane Positioning	68	-0.04	-0.04	
I-680	37°49.211700 N	121°59.605392 W	Erratic Lane Positioning	67	-0.02	0.01	"Ping-ponging" within lane during curve
I-680	37°42.364068 N	121°55.574550 W	Other	67	0.01	-0.11	System disengagement
I-580	37°42.091482 N	121°55.029750 W	Erratic Lane Positioning	67	0.25	-0.07	
I-580	37°42.093456 N	121°54.806988 W	Erratic Lane Positioning	67	0.05	-0.02	"Ping-ponging" within lane
I-580	37°42.077352 N	121°52.888956 W	Erratic Lane Positioning	67	0.03	-0.06	
I-580	37°42.065502 N	121°51.016464 W	Erratic Lane Positioning	68	-0.08	-0.08	Too close to tractor trailer alongside
I-580	37°42.032724 N	121°47.653206 W	Erratic Lane Positioning	67	-0.02	-0.20	
I-580	37°41.982558 N	121°46.974648 W	Erratic Lane Positioning	68	0.05	0.03	
I-580	37°42.162372 N	121°45.382578 W	Erratic Lane Positioning	64	-0.01	0.03	
I-580	37°42.153828 N	121°44.393832 W	Erratic Lane Positioning	68	0.02	0.05	
I-580	37°42.236274 N	121°44.131866 W	Other	60	0.08	-0.08	
I-580	37°43.029804 N	121°42.185136 W	Erratic Lane Positioning	67	-0.06	0.05	More ping ponging
I-580	37°43.074330 N	121°41.979090 W	Other	62	-0.07	-0.03	
I-580	37°43.081284 N	121°41.945604 W	Lane Departure	59	-0.09	0.03	Lane departure left side
I-580	37°43.783452 N	121°37.909002 W	Erratic Lane Positioning	61	0.03	0.06	
I-580	37°43.973346 N	121°37.752048 W	Erratic Lane Positioning	58	0.06	-0.07	
I-580	37°44.500770 N	121°34.414218 W	Erratic Lane Positioning	67	-0.04	0.02	
I-5	37°34.496334 N	121°18.787446 W	Erratic Lane Positioning	72	0.00	0.03	"Ping-ponging" within lane
I-5	37°28.863750 N	121°11.884014 W	Erratic Lane Positioning	72	-0.04	0.01	
I-5	37°24.300954 N	121°8.623842 W	Erratic Lane Positioning	73	0.02	0.00	
I-5	37°23.116068 N	121°7.807014 W	Erratic Lane Positioning	73	-0.08	-0.05	
I-5	37°18.227316 N	121°6.231714 W	Erratic Lane Positioning	73	-0.05	0.03	
I-5	37°14.949606 N	121°5.392860 W	Erratic Lane Positioning	72	-0.07	-0.03	
I-5	37°3.548988 N	120°58.345116 W	Erratic Lane Positioning	73	0.01	0.03	
I-5	37°3.418056 N	120°58.218198 W	Erratic Lane Positioning	73	0.00	-0.07	
I-5	37°2.769816 N	120°57.590754 W	Erratic Lane Positioning	68	0.05	0.03	
I-5	36°59.516646 N	120°54.498156 W	Erratic Lane Positioning	73	-0.03	-0.02	
I-5	36°55.506192 N	120°50.120124 W	Erratic Lane Positioning	73	0.04	-0.02	
I-5	36°46.825320 N	120°43.567476 W	Erratic Lane Positioning	74	-0.04	-0.03	
I-5	36°46.641186 N	120°43.441050 W	Erratic Lane Positioning	74	0.02	-0.06	
I-5	36°41.281044 N	120°39.615786 W	Erratic Lane Positioning	74	0.03	-0.01	
I-5	36°30.742878 N	120°27.981870 W	Other	66	0.01	0.03	System disengagement
I-5	36°28.231104 N	120°25.602906 W	Lane Departure	75	-0.01	-0.02	Lane departure left side
I-5	36°17.754198 N	120°16.224522 W	Erratic Lane Positioning	75	0.09	-0.18	System wanted to follow the exit with disengagement
I-5	36°5.550318 N	120°7.067340 W	Erratic Lane Positioning	75	-0.02	0.03	Started ping ponging in the lane and disengaged

Figure 56: Data from all noted events during naturalistic evaluation of the 2019 BMW X7 Image Source: AAA



Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-5	35°30.487452 N	119°32.639616 W	Erratic Lane Positioning	73	0.02	-0.02	
I-5	35°17.660880 N	119°15.234372 W	Lane Departure	75	-0.02	0.01	Left side
I-5	35°15.869424 N	119°13.325052 W	Erratic Lane Positioning	75	-0.02	-0.06	
I-5	35°1.271136 N	118°57.573984 W	Erratic Lane Positioning	75	0.00	-0.07	
I-5	34°10.529046 N	118°18.429120 W	Other	32	0.09	-0.11	Abruptly slowed without obvious cause
I-5	34°2.459874 N	118°16.435302 W	Erratic Lane Positioning	53	-0.07	0.05	"Ping-ponging" within curve

Figure 57: Data from all noted events during naturalistic evaluation of the 2019 BMW X7 Image Source: AAA



BMW X7	L2 Project Subjective Ratings										
	Driver 1		Driver 2		Driver 3		Driver 4		Driver 5		Totals/Avg
	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	
<u>FCW warning timing</u>		n/a	n/a		n/a	n/a		n/a	n/a	n/a	
1. Too late											0
2. Just right	1			1			1				3
3. Too early											0
<u>LDW warning timing</u>											
1. Too late		1	1					1		1	4
2. Just right	1			1	1	1	1		1		6
3. Too early											0
<u>Comfort of ACC braking</u>											
1. Too late				1							1
2. Just right	1	1	1		1	1	1	1	1	1	9
3. Too early											0
<u>Comfort of ACC acceleration</u>											
1. Too slow											0
2. Just right	1	1	1	1	1	1	1	1	1	1	10
3. Too fast											0
<u>Lane Keeping Correction</u>											
1. Too much correction	1			1			1	1	1	1	6
2. Just right		1	1		1	1					4
3. Not enough or no correction											0
<u>Please rate the following from 1 to 5, where 5 is the best</u>											
Awareness of system enabled	4	4	4	4	3	5	5	5	5	4	4.3
Awareness of system disengaged	3	4	4	3	3	5	5	5	5	4	4.1
Understanding of warnings	4	4	4	3	4	4	5	5	4	4	4.1
<u>For ACC, which headway setting did you feel most comfortable using?</u>											
1. Smallest	1	1	1				1	1			5
2. Middle				1	1	1			1	1	5
3. Largest											0
<u>For Lane Centering, what was the tendency of the system</u>											
1. Stay in the middle	1	1	1	1	1	1	1	1	1	1	10
2. Hug the left of the lane											0
3. Hug the right of the lane											0
<u>For Lane Centering, did the system</u>											
1. Complement the drive	1	1	1		1	1	1				6
2. Neither enhance or detract				1				1			2
3. Fight the wheel									1	1	2
Overall Trust of the Level 2 system	4	4	3	3	3	4	4	3	4	3	4
<u>Did the Level 2 system enhance the driving experience during highway driving?</u>											
<u>In Traffic?</u>	n/a										
1. Yes		1	1		1	1	1	1	1	1	8
2. Neither enhance or detract				1							1
3. No											0
<u>In Non-Traffic?</u>											
1. Yes	1	1	1	1	1	1	1		1	1	9
2. Neither enhance or detract											0
3. No								1			1

Figure 58: Subjective ratings during naturalistic evaluation of the 2019 BMW X7 Image Source: AAA



## 11.2 2019 Cadillac CT6

Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-680	37°48.684952	121°59.581153	Other	62	-0.95	-0.20	Deceleration due to overpass
I-680	37°47.550915	121°58.996371	Other	72	0.70	-0.26	Acceleration due to overpass
I-680	37°46.782208	121°58.600374	Other	74	0.34	0.67	Acceleration due to overpass
I-680	37°46.628119	121°58.522764	Other	73	0.28	-0.02	Acceleration due to overpass
I-680	37°46.279173	121°58.346697	Other	61	-0.68	0.18	Deceleration due to overpass
I-680	37°45.602071	121°57.935185	Other	70	0.25	0.01	Acceleration due to overpass
I-680	37°43.410894	121°56.421972	Other	55	-1.00	0.55	Deceleration due to overpass
Hwy 101	37°42.55569	121°31.12062	Other	64	-0.04	0.10	Disengagement - unknown
Hwy 101	36°51.707388	121°34.9044892	Lane Departure	74	0.05	-0.07	Disengagement - unknown
Hwy 101	36°41.258154	121°39.244044	Other	68	0.03	0.04	Disengagement - lost lane line
Hwy 101	36°41.075604	121°38.896104	Other	71	0.27	-0.12	Disengagement - lost lane line
Hwy 101	36°36.562866	121°33.757944	Other	68	0.04	-0.05	Disengagement - lost lane line
Hwy 101	36°35.753016	121°32.763222	Other	69	0.03	-0.01	Disengagement - lost lane line
Hwy 101	36°34.39302	121°31.332918	Other	66	-0.05	0.03	Disengagement - unknown
Hwy 101	36°33.074988	121°29.960634	Other	73	0.06	-0.08	Disengagement - lost lane line
Hwy 101	36°24.35115	121°19.087488	Other	72	0.10	0.20	Disengagement - unknown
Hwy 101	36°24.02223	121°18.882606	Other	73	-0.03	0.01	Disengagement - unknown
Hwy 101	36°19.902642	121°14.81343	Other	72	-0.07	0.02	Disengagement - unknown
Hwy 101	36°18.582588	121°13.853136	Other	72	0.04	0.06	Disengagement - unknown
Hwy 101	36°12.416754	121°9.549648	Other	70	0.04	0.04	Disengagement - unknown - passing semitruck
Hwy 101	36°12.156852	121°8.526618	Other	64	-0.02	0.04	Disengagement - unknown - crossing overpass/bridge
Hwy 101	36°19.1931	121°14.125704	Other	73	-0.02	0.12	Disengagement - inattention - error
Hwy 101	36°24.722118	121°19.198026	Other	74	0.00	-0.04	Disengagement - inattention - error
Hwy 101	36°24.877542	121°19.24866	Other	74	-0.01	0.03	Disengagement - inattention - error
Hwy 101	36°36.773202	121°34.023708	Other	68	-0.03	0.07	Disengagement - unknown
Hwy 101	36°40.724886	121°38.485584	Other	58	0.04	0.08	Disengagement - lost lane line
Hwy 101	36°44.213524	121°39.43783	Other	62	-0.05	0.06	Disengagement - inattention - error
Hwy 101	36°46.850152	121°40.159374	Other	71	-0.02	-0.09	Disengagement - inattention - error
Hwy 101	36°48.09311	121°39.620814	Other	62	-0.07	-0.04	Disengagement - unknown
Hwy 101	36°54.06462	121°33.388704	Other	59	-0.67	-0.05	Disengagement - approaching traffic
Hwy 101	36°54.692916	121°33.235152	Other	71	-0.02	-0.05	Disengagement - approaching traffic
Hwy 101	36°56.945106	121°33.16356	Other	23	0.01	0.06	Disengagement - inattention - error
Hwy 101	36°59.349492	121°33.467436	Other	73	-0.03	0.01	Disengagement - inattention - error
Hwy 101	36°59.729046	121°33.39372	Other	72	-0.03	0.01	Disengagement - inattention - error
I-680	37°31.717312	121°56.691784	Other	32	-0.07	-0.04	Disengagement - approaching traffic
I-680	37°33.243042	121°55.006062	Other	61	-0.03	-0.05	Disengagement - unknown
I-680	37°33.750024	121°54.292428	Lane Departure	74	-0.06	0.11	Lane Departure + disengagement
I-680	37°34.993938	121°52.42239	Other	75	-0.01	0.02	Disengagement - inattention - error
I-680	37°36.068588	121°52.327432	Other	75	0.00	0.14	Unable to engage
I-5	34°53.559354	118°55.023462	Other	59	-0.10	0.08	Disengagement - unknown - passing semitruck
I-5	34°50.348874	118°51.793812	Other	69	-0.05	-0.10	Disengagement - approaching traffic - on turn
I-5	34°26.280792	118°35.78235	Other	73	-0.07	-0.06	Disengagement - unknown - on turn
I-5	34°22.467708	118°33.778026	Other	74	-0.01	-0.01	Unable to engage
I-5	34°16.478004	118°27.045114	Erratic Lane Positioning	70	0.08	-0.11	Erratic Lane Position - unusual double white marker
I-5	34°15.563862	118°26.281896	Erratic Lane Positioning	70	-0.07	0.03	Erratic Lane Position - narrow lanes - no left shoulder
I-5	34°13.81548	118°23.785818	Erratic Lane Positioning	70	0.02	-0.11	Erratic Lane Position - unusual double white marker
I-5	34°13.601148	118°23.28789	Erratic Lane Positioning	70	0.05	0.37	Erratic Lane Position - unusual double white marker (HOV?)
I-5	34°13.477224	118°22.402272	Erratic Lane Positioning	70	0.07	0.04	Erratic Lane Position - unusual double white marker (HOV?)
I-5	34°13.319832	118°22.018206	Erratic Lane Positioning	70	0.08	0.14	Erratic Lane Position - overpass
I-5	34°12.324186	118°20.550954	Other	67	-0.04	0.04	Disengagement - slow adjacent traffic
I-5	34°10.92471	118°18.89328	Other	39	0.08	0.00	Disengagement - approaching traffic
I-5	34°4.896402	118°13.69017	Other	13	0.05	-0.04	Unable to engage - lockout - inattention

Figure 59: Data from all noted events during naturalistic evaluation of the 2019 Cadillac CT6 Image Source: AAA



Cadillac CT6	L2 Project Subjective Ratings										
	Driver 1		Driver 2	Driver 3	Driver 4		Driver 5		Driver 6		Totals/Avg
	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	
FCW warning timing	n/a		n/a		n/a		n/a			n/a	
1. Too late											0
2. Just right		1		1		1			1		4
3. Too early								1			1
LDW warning timing	n/a						n/a	n/a			
1. Too late										1	1
2. Just right		1	1	1	1	1	1		1		7
3. Too early											0
Comfort of ACC braking											
1. Too late											0
2. Just right		1	1	1	1	1	1	1	1	1	9
3. Too early	1										1
Comfort of ACC acceleration											
1. Too slow	1										1
2. Just right		1	1	1	1	1	1	1	1	1	9
3. Too fast											0
Lane Keeping Correction											
1. Too much correction											0
2. Just right	1	1	1	1	1	1	1	1	1	1	10
3. Not enough or no correction											0
Please rate the following from 1 to 5, where 5 is the best											
Awareness of system enabled	5	5	5	5	4	5	5	5	5	4	4.8
Awareness of system disengaged	5	5	5	4	4	4	5	5	4	5	4.6
Understanding of warnings	5	5	4	4	4	4	5	4	4	4	4.3
For ACC, which headway setting did you feel most comfortable using?											
1. Smallest	1	1	1	1			1	1	1		7
2. Middle					1	1				1	3
3. Largest											0
For Lane Centering, what was the tendency of the system											
1. Stay in the middle	1	1	1	1	1	1	1	1	1	1	10
2. Hug the left of the lane											0
3. Hug the right of the lane											0
For Lane Centering, did the system											
1. Compliment the drive	1	1	1	1	1	1	1	1		1	9
2. Neither enhance or detract									1		1
3. Fight the wheel											0
Overall Trust of the Level 2 system	4	4	3	3	4	4	4	4	4	4	4
Did the Level 2 system enhance the driving experience during highway driving?											
In Traffic?		n/a		n/a					n/a		
1. Yes	1				1	1	1	1		1	6
2. Neither enhance or detract											0
3. No			1								1
In Non-Traffic?											
1. Yes	1	1	1	1	1	1	1	1	1	1	10
2. Neither enhance or detract											0
3. No											0

Figure 60: Subjective ratings during naturalistic evaluation of the 2019 Cadillac CT6 Image Source: AAA



## 11.3 2019 Ford Edge

Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
Hwy 101	34°12.536568 N	118°24.395706 W	Erratic Lane Positioning	70	0.01	0.10	
Hwy 101	34°14.053212 N	118°24.623868 W	Lane Departure	74	-0.05	0.27	
Hwy 101	34°24.183468 N	118°42.321060 W	Lane Departure	69	0.06	0.01	
Hwy 101	34°24.402348 N	118°44.334024 W	Lane Departure	67	0.01	-0.05	
Hwy 101	34°25.252866 N	119°36.451056 W	Lane Departure	68	-0.05	-0.07	
Hwy 101	34°25.377024 N	119°39.300372 W	Lane Departure	67	0.28	0.16	Occurred during lane change with right turn signal
Hwy 101	34°26.475336 N	119°45.631764 W	Erratic Lane Positioning	71	0.09	-0.22	Vehicle tracking right in lane
Hwy 101	34°25.947108 N	119°54.323016 W	Lane Departure	71	-0.02	-0.10	Lane Departure turned off while approaching lane split
Hwy 101	34°26.346774 N	119°55.925736 W	Erratic Lane Positioning	70	0.00	0.03	
Hwy 101	34°27.840996 N	120°2.607564 W	Erratic Lane Positioning	69	-0.05	-0.06	
Hwy 101	34°28.304346 N	120°10.500090 W	Lane Departure	71	0.05	-0.07	No lane departure warning, vehicle crossed right lane marker
Hwy 101	34°28.413432 N	120°11.981898 W	Erratic Lane Positioning	71	-0.03	0.10	
Hwy 101	34°29.148366 N	120°13.702614 W	Other	65	-0.04	-0.13	System disengaged during turn, solid lines on both sides
Hwy 101	34°29.853762 N	120°13.852308 W	Erratic Lane Positioning	55	0.08	-0.09	Approaching exit, vehicle wanted to continue exiting, driver had to intervene with system active
Hwy 101	34°31.636926 N	120°11.850750 W	Lane Departure	66	0.00	0.02	Vehicle veered to left
Hwy 101	34°32.879772 N	120°11.536638 W	Lane Departure	66	0.03	0.04	Lane departure with system still active
Hwy 101	34°34.299942 N	120°11.560050 W	Erratic Lane Positioning	66	-0.04	-0.28	
Hwy 101	34°34.965162 N	120°11.625492 W	Erratic Lane Positioning	60	-0.05	-0.16	Vehicle hugging lane marker
Hwy 101	34°36.634584 N	120°11.416728 W	Lane Departure	71	0.01	0.01	System disengagement with simultaneous lane departure
Hwy 101	34°37.422798 N	120°11.331612 W	Erratic Lane Positioning	71	-0.01	-0.02	
Hwy 101	34°44.589672 N	120°16.290984 W	Erratic Lane Positioning	62	-0.01	-0.05	
Hwy 101	34°52.618584 N	120°24.357438 W	Lane Departure	74	0.00	-0.08	
Hwy 101	35°15.510582 N	120°40.428594 W	Erratic Lane Positioning	64	-0.10	0.09	There was an onramp right there and it tried to swing right
Hwy 101	35°17.502324 N	120°39.362736 W	Lane Departure	67	0.02	-0.20	Through that turn, on the right line and reflectors
Hwy 101	35°18.930864 N	120°37.313346 W	Lane Departure	65	-0.11	0.13	Current lane opened up to 2 lanes, it decided to go in the right lane
Hwy 101	35°20.945436 N	120°37.856910 W	Lane Departure	70	-0.04	0.13	As we crested this hill, it pulled to the left and was actually on the line running over the reflectors
Hwy 101	35°21.587910 N	120°38.264280 W	Lane Departure	64	-0.01	-0.04	Coming down the hill, kept pulling to the right there and crossed the line
Hwy 101	35°47.407758 N	120°43.834236 W	Failure to Slow/Stop	44	-0.10	0.03	All of a sudden, it started accelerating and there was a car in front of me
Hwy 101	36°11.083584 N	121°4.130376 W	Erratic Lane Positioning	57	0.02	0.04	A little close to the left for comfort and it wanted to take the exit back there.
Hwy 101	36°11.142102 N	121°4.190070 W	Erratic Lane Positioning	57	-0.01	-0.08	Way too close to comfort. K-rail is right on left lane marking.
Hwy 101	36°11.244306 N	121°4.309020 W	Erratic Lane Positioning	59	0.07	0.04	Way too close to comfort. K-rail is right on left lane marking.
Hwy 101	36°11.427306 N	121°4.655040 W	Other	61	-0.01	0.04	System disengaged
Hwy 101	36°11.770998 N	121°5.738586 W	Other	58	0.03	0.03	System will not engage on this road
Hwy 101	36°12.254670 N	121°8.097162 W	Erratic Lane Positioning	61	-0.01	0.02	Vehicle darted to the exit
Hwy 101	36°22.713696 N	121°17.691756 W	Erratic Lane Positioning	72	-0.04	0.01	Lane Departure on the left
Hwy 101	36°25.997910 N	121°20.279430 W	Erratic Lane Positioning	72	0.04	0.22	Hugging lane on left
Hwy 101	36°27.460494 N	121°22.608204 W	Erratic Lane Positioning	67	-0.02	-0.05	Hugging left side of lane with a vehicle passing
Hwy 101	36°31.449666 N	121°27.938808 W	Lane Departure	71	-0.02	-0.03	Lane departure on the left
Hwy 101	36°31.935012 N	121°28.562880 W	Other	72	-0.03	0.00	System disengaged, poor lane markers
Hwy 101	36°34.323714 N	121°31.239138 W	Lane Departure	71	-0.09	0.06	Lane departure on the right
Hwy 101	36°35.277054 N	121°32.254668 W	Erratic Lane Positioning	68	-0.05	-0.05	Too close to the right with a tractor trailer on the side
Hwy 101	36°36.176778 N	121°33.211254 W	Other	71	0.05	-0.01	Car wanted to follow truck to the right lane
Hwy 101	36°40.948776 N	121°38.641746 W	Other	60	0.04	0.03	System disengaged, no lane markers
Hwy 101	36°41.651898 N	121°39.748536 W	Other	61	0.00	-0.12	System disengaged
Hwy 101	36°46.693146 N	121°40.173456 W	Lane Departure	69	0.01	0.03	Lane departure left side
Hwy 101	36°48.861846 N	121°38.414358 W	Lane Departure	74	0.02	-0.13	Lane departure right side
Hwy 101	36°48.991086 N	121°38.182596 W	Erratic Lane Positioning	74	0.06	0.08	Hugging right side of road
Hwy 101	36°49.221858 N	121°37.840296 W	Other	56	-0.04	0.18	Inappropriate heavy acceleration into corner
Hwy 101	36°50.218092 N	121°37.846074 W	Erratic Lane Positioning	67	-0.02	0.00	Hugging left side
Hwy 101	36°50.333610 N	121°37.900842 W	Erratic Lane Positioning	64	-0.03	0.02	Ping ponging within lane
Hwy 101	36°51.012396 N	121°38.158458 W	Erratic Lane Positioning	64	0.06	-0.06	Hugging right side of road with gas truck alongside
Hwy 101	36°51.715176 N	121°37.117008 W	Erratic Lane Positioning	72	-0.17	0.13	Hugging left side of road
Hwy 101	36°51.613080 N	121°36.514944 W	Erratic Lane Positioning	62	0.32	1.54	Hugging left side
Hwy 101	36°51.609534 N	121°36.422520 W	Erratic Lane Positioning	63	0.11	1.18	Steering towards guardrail
Hwy 101	36°51.576888 N	121°36.084576 W	Erratic Lane Positioning	68	0.06	-0.02	Left side
Hwy 101	36°51.700380 N	121°34.791126 W	Erratic Lane Positioning	63	0.08	0.15	Left side
Hwy 101	36°55.798572 N	121°32.895456 W	Lane Departure	64	-0.05	0.02	Left side
Hwy 101	37°3.875982 N	121°35.201940 W	Lane Departure	70	0.06	-0.01	
Hwy 101	37°8.201178 N	121°38.199228 W	Erratic Lane Positioning	63	-0.02	0.10	
I-680	37°29.630316 N	121°55.269678 W	Lane Departure	6	0.03	0.01	
I-680	37°30.792306 N	121°56.327874 W	Erratic Lane Positioning	9	-0.10	0.02	
I-680	37°31.041732 N	121°56.469690 W	Erratic Lane Positioning	8	0.01	0.00	
I-680	37°42.188166 N	121°55.410234 W	Erratic Lane Positioning	73	-0.02	0.12	
I-680	37°53.601462 N	122°3.972486 W	Lane Departure	67	-0.04	-0.01	Severe lane departure to the left
I-680	37°52.664142 N	122°2.886468 W	Lane Departure	69	-0.02	-0.03	Left lane departure about 10 seconds ago
I-680	37°51.828594 N	122°2.181210 W	Lane Departure	71	0.02	0.01	Lane departure with passing traffic
I-680	37°48.508458 N	121°59.507730 W	Lane Departure	66	-0.08	-0.11	Lane departure with vehicles alongside
I-680	37°46.411704 N	121°58.413204 W	Lane Departure	71	0.01	0.06	System disengagement
I-680	37°46.197684 N	121°58.307190 W	Lane Departure	71	0.04	-0.03	System hugging right lane
I-680	37°46.015050 N	121°58.204296 W	Other	71	0.08	-0.03	System disengagement. Sun angle likely a factor.
I-680	37°45.879528 N	121°58.115490 W	Other	71	0.07	-0.04	System will not engage. Sun angle likely a factor.
I-680	37°45.224016 N	121°57.688326 W	Other	70	0.05	0.04	System will not engage. Sun angle likely a factor.
I-680	37°43.829676 N	121°56.747508 W	Erratic Lane Positioning	71	0.02	-0.01	System favoring right lane marker
I-680	37°43.581600 N	121°56.554470 W	Other	70	0.01	-0.07	System disengagement. Sun angle likely a factor.
I-580	37°42.060090 N	121°50.429533 W	Erratic Lane Positioning	71	0.02	0.12	Hugging left lane marker with semi alongside
I-580	37°42.048072 N	121°48.994944 W	Lane Departure	70	-0.03	0.08	Lane departure left side unexpectedly with vehicle alongside
I-580	37°42.009078 N	121°47.531118 W	Lane Departure	71	0.08	0.03	Lane departure right side in a corner
I-580	37°44.289552 N	121°33.396750 W	Lane Departure	65	-0.03	-0.03	Lane departure right side. Sun angle likely a factor.
I-580	37°43.918302 N	121°32.966526 W	Other	66	-0.01	-0.02	System will not engage. Sun angle likely a factor.

Figure 61: Subjective ratings during naturalistic evaluation of the 2019 Ford Edge Image Source: AAA



Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-580	37°42.230724 N	121°30.587646 W	Other	78	-0.06	0.01	System will not engage. Sun angle likely a factor.
I-5	37°34.912026 N	121°19.328142 W	Other	78	-0.02	-0.04	System will not engage. Sun angle likely a factor.
I-5	37°32.340396 N	121°15.995538 W	Other	78	0.03	-0.04	System will not engage. Sun angle likely a factor.
I-5	37°24.131496 N	121°8.507748 W	Erratic Lane Positioning	73	0.06	-0.02	
I-5	37°23.921046 N	121°8.361372 W	Erratic Lane Positioning	72	-0.06	-0.06	
I-5	37°21.009258 N	121°7.094832 W	Erratic Lane Positioning	73	0.03	-0.02	Vehicle swerved to the right
I-5	37°16.365186 N	121°5.753754 W	Erratic Lane Positioning	73	-0.07	0.10	
I-5	36°30.094284 N	120°27.328512 W	Other	74	-0.01	0.02	Hugging left side of lane
I-5	36°28.421358 N	120°25.783758 W	Erratic Lane Positioning	67	0.01	0.03	
I-5	36°27.103842 N	120°24.525624 W	Erratic Lane Positioning	74	-0.01	-0.03	
I-5	36°21.104850 N	120°19.155132 W	Lane Departure	76	-0.05	-0.12	Lane departure left side
I-5	36°18.069822 N	120°16.496868 W	Erratic Lane Positioning	68	-0.01	-0.03	
I-5	36°16.631100 N	120°15.514314 W	Erratic Lane Positioning	80	0.04	0.03	
I-5	36°15.451998 N	120°14.774142 W	Lane Departure	74	-0.02	0.05	Lane departure right side
I-5	36°14.877840 N	120°14.410806 W	Erratic Lane Positioning	70	-0.01	0.01	
I-5	36°12.891660 N	120°13.161000 W	Erratic Lane Positioning	78	0.04	0.05	
I-5	36°11.351652 N	120°12.189882 W	Erratic Lane Positioning	74	-0.02	-0.04	
I-5	36°10.556712 N	120°11.641092 W	Erratic Lane Positioning	74	0.01	0.02	
I-5	36°8.453970 N	120°9.722640 W	Lane Departure	74	-0.06	0.11	Lane departure right side upon approaching exit
I-5	36°8.077602 N	120°9.376572 W	Lane Departure	74	0.00	-0.10	
I-5	36°8.049852 N	120°9.352542 W	Lane Departure	74	-0.03	-0.05	
I-5	36°7.906770 N	120°9.221496 W	Lane Departure	74	0.05	-0.02	Overcorrects, tries to correct itself, resulting in "ping-ponging". Left then right lane departure.
I-5	36°5.552826 N	120°7.072464 W	Lane Departure	74	-0.02	0.01	Lane departure right side upon approaching exit
I-5	36°5.365356 N	120°6.900570 W	Erratic Lane Positioning	74	-0.01	0.09	
I-5	36°3.720654 N	120°4.668384 W	Erratic Lane Positioning	78	-0.09	-0.01	Hugging right side of lane
I-5	35°54.742848 N	119°53.376366 W	Lane Departure	78	0.02	0.00	Left side
I-5	35°53.362422 N	119°51.968244 W	Lane Departure	75	0.07	-0.04	Left side
I-5	35°53.281998 N	119°51.888294 W	Lane Departure	75	-0.05	-0.07	Left side
I-5	35°53.026002 N	119°51.644370 W	Erratic Lane Positioning	75	-0.04	-0.07	
I-5	35°52.789578 N	119°51.420468 W	Lane Departure	75	-0.02	0.05	
I-5	35°52.364682 N	119°51.017340 W	Erratic Lane Positioning	75	0.02	-0.04	
I-5	35°52.168542 N	119°50.831034 W	Lane Departure	75	0.02	0.02	Left side
I-5	35°51.746874 N	119°50.432376 W	Erratic Lane Positioning	75	-0.04	0.00	
I-5	35°50.585514 N	119°49.393872 W	Erratic Lane Positioning	75	0.08	-0.04	
I-5	35°50.496780 N	119°49.321422 W	Erratic Lane Positioning	75	0.01	0.00	
I-5	35°50.145552 N	119°49.036218 W	Erratic Lane Positioning	73	-0.02	0.09	
I-5	35°49.643328 N	119°48.650418 W	Lane Departure	72	0.01	-0.06	Right side
I-5	35°46.449666 N	119°46.267140 W	Erratic Lane Positioning	77	-0.03	0.01	
I-5	35°45.933312 N	119°45.881910 W	Erratic Lane Positioning	77	0.00	0.01	
I-5	35°41.885184 N	119°42.864870 W	Erratic Lane Positioning	77	-0.06	0.04	
I-5	35°40.837536 N	119°42.082446 W	Erratic Lane Positioning	77	0.01	0.06	
I-5	35°40.188642 N	119°41.599620 W	Erratic Lane Positioning	77	-0.01	-0.07	
I-5	35°39.943464 N	119°41.415888 W	Erratic Lane Positioning	76	0.01	-0.22	
I-5	35°39.358260 N	119°40.979700 W	Erratic Lane Positioning	75	-0.01	-0.02	
I-5	35°39.225480 N	119°40.880514 W	Erratic Lane Positioning	75	-0.06	0.05	
I-5	35°37.654506 N	119°39.717570 W	Erratic Lane Positioning	77	-0.14	0.03	
I-5	35°37.553202 N	119°39.641658 W	Erratic Lane Positioning	76	0.02	0.02	
I-5	35°37.415178 N	119°39.538920 W	Erratic Lane Positioning	75	-0.02	-0.08	
I-5	35°36.185724 N	119°38.588286 W	Lane Departure	74	-0.02	0.01	Left side
I-5	35°35.067480 N	119°37.516326 W	Lane Departure	74	0.01	-0.04	Left side
I-5	35°34.880862 N	119°37.336830 W	Lane Departure	74	0.04	-0.08	Left side
I-5	35°34.779138 N	119°37.240584 W	Other	74	0.01	-0.04	Having a hard time keeping/picking up the center line.
I-5	35°32.954676 N	119°35.324754 W	Erratic Lane Positioning	74	0.02	0.00	
I-5	35°31.796610 N	119°34.063764 W	Lane Departure	74	0.00	0.03	Left side
I-5	35°31.624554 N	119°33.876498 W	Lane Departure	74	0.04	-0.04	Left side
I-5	35°30.684618 N	119°32.854674 W	Erratic Lane Positioning	74	0.00	0.03	
I-5	35°30.611064 N	119°32.775456 W	Erratic Lane Positioning	74	-0.02	0.05	
I-5	35°30.303006 N	119°32.440716 W	Erratic Lane Positioning	74	0.03	0.07	
I-5	35°30.267330 N	119°32.401272 W	Lane Departure	74	0.01	0.07	Right side
I-5	35°29.821734 N	119°31.917036 W	Lane Departure	74	0.04	0.00	Right side
I-5	35°29.504406 N	119°31.513902 W	Erratic Lane Positioning	74	0.01	-0.07	
I-5	35°29.417982 N	119°31.394598 W	Erratic Lane Positioning	74	-0.05	0.02	
I-5	35°29.173470 N	119°31.061310 W	Erratic Lane Positioning	74	0.04	-0.04	
I-5	35°29.072778 N	119°30.922374 W	Erratic Lane Positioning	74	-0.01	0.01	
I-5	35°28.785852 N	119°30.527418 W	Erratic Lane Positioning	74	0.01	0.01	
I-5	35°28.770414 N	119°30.506202 W	Lane Departure	74	0.09	-0.09	Lane departure left side from previous event.
I-5	35°28.018980 N	119°29.471250 W	Erratic Lane Positioning	74	0.01	-0.05	
I-5	35°27.576486 N	119°28.862904 W	Lane Departure	74	0.01	0.01	Left side
I-5	35°26.783028 N	119°27.766908 W	Erratic Lane Positioning	74	0.05	0.02	
I-5	35°26.685708 N	119°27.633162 W	Erratic Lane Positioning	74	-0.02	0.03	
I-5	35°26.583804 N	119°27.492732 W	Erratic Lane Positioning	74	0.04	0.06	
I-5	35°26.418774 N	119°27.266184 W	Lane Departure	74	-0.03	-0.01	Left side
I-5	35°22.326282 N	119°21.637320 W	Lane Departure	74	0.02	-0.05	Right side
I-5	35°21.505002 N	119°20.476638 W	Erratic Lane Positioning	68	0.03	-0.02	
I-5	35°20.945196 N	119°19.684944 W	Erratic Lane Positioning	74	0.03	0.03	
I-5	35°19.629858 N	119°17.831316 W	Lane Departure	74	0.02	-0.01	
I-5	35°18.870432 N	119°16.760172 W	Lane Departure	74	-0.01	-0.16	Left side
I-5	35°18.766014 N	119°16.616820 W	Lane Departure	74	-0.05	0.03	Left side
I-5	35°14.213346 N	119°11.558700 W	Lane Departure	74	-0.01	-0.05	Left side
I-5	35°11.493030 N	119°8.652174 W	Lane Departure	74	0.00	-0.01	Right side
I-5	35°11.348166 N	119°8.490264 W	Erratic Lane Positioning	74	0.01	-0.06	

Figure 62: Subjective ratings during naturalistic evaluation of the 2019 Ford Edge Image Source: AAA



Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-5	35°10.478214 N	119°7.526802 W	Erratic Lane Positioning	74	0.02	-0.05	
I-5	35°9.778500 N	119°6.754164 W	Lane Departure	74	0.00	0.10	Right side
I-5	35°7.940688 N	119°4.719192 W	Lane Departure	74	-0.05	0.02	Left side
I-5	35°6.909594 N	119°3.580344 W	Erratic Lane Positioning	74	0.01	0.03	
I-5	35°6.189288 N	119°2.784618 W	Erratic Lane Positioning	74	-0.07	0.05	
I-5	35°5.395824 N	119°1.929018 W	Erratic Lane Positioning	74	0.03	-0.11	
I-5	35°5.235150 N	119°1.756764 W	Lane Departure	74	-0.01	0.00	
I-5	35°4.419282 N	119°0.883932 W	Erratic Lane Positioning	74	-0.08	0.08	
I-5	35°4.391598 N	119°0.853626 W	Lane Departure	74	0.14	-0.11	Lane departure right side from previous event.
I-5	34°53.418864 N	118°54.811638 W	Other	57	-0.04	0.00	Hugging left side of lane in turn
I-5	34°47.762460 N	118°51.664686 W	Other	69	-0.04	-0.06	
I-5	34°29.632452 N	118°37.352646 W	Lane Departure	71	0.00	0.01	Left side

Figure 63: Subjective ratings during naturalistic evaluation of the 2019 Ford Edge Image Source: AAA



Ford Edge	L2 Project Subjective Ratings										
	Driver 1		Driver 2	Driver 3	Driver 4		Driver 5		Driver 6		Totals/Avg
	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	
FCW warning timing	n/a	n/a			n/a	n/a	n/a	n/a	n/a	n/a	
1. Too late			1								1
2. Just right				1							1
3. Too early											0
LDW warning timing											
1. Too late	1	1	1	1			1	1	1	1	8
2. Just right					1	1					2
3. Too early											0
Comfort of ACC braking											
1. Too late				1			1		1		3
2. Just right	1	1			1	1		1		1	6
3. Too early			1								1
Comfort of ACC acceleration											
1. Too slow		1							1		2
2. Just right	1		1	1	1	1	1	1		1	8
3. Too fast											0
Lane Keeping Correction											
1. Too much correction											0
2. Just right						1					1
3. Not enough or no correction	1	1	1	1	1		1	1	1	1	9
Please rate the following from 1 to 5, where 5 is the best											
Awareness of system enabled	3	4	2	3	4	3	3	3	3	3	3.1
Awareness of system disengaged	3	3	2	3	4	3	3	3	4	2	3
Understanding of warnings	4	3	2	3	4	4	5	5	3	3	3.6
For ACC, which headway setting did you feel most comfortable using?											
1. Smallest	1	1	1	1			1	1			6
2. Middle					1	1			1	1	4
3. Largest											0
For Lane Centering, what was the tendency of the system											
1. Stay in the middle											0
2. Hug the left of the lane	1			1	1	1		1	1	1	7
3. Hug the right of the lane		1	1				1				3
For Lane Centering, did the system											
1. Compliment the drive					1	1					2
2. Neither enhance or detract	1	1						1			3
3. Fight the wheel			1	1			1		1	1	5
Overall Trust of the Level 2 system	2	2	1	1	4	4	1	2	3	2	2
Did the Level 2 system enhance the driving experience during highway driving?											
In Traffic?	n/a	n/a					n/a	n/a		n/a	
1. Yes			1		1	1					3
2. Neither enhance or detract											0
3. No				1					1		2
In Non-Traffic?											
1. Yes					1	1					2
2. Neither enhance or detract	1	1						1			3
3. No			1	1			1		1	1	5

Figure 64: Subjective ratings during naturalistic evaluation of the 2019 Ford Edge Image Source: AAA



## 11.4 2020 Kia Telluride

Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
Hwy 101	34°6.970950 N	118°20.210160 W	Lane Departure	58	0.00	-0.05	Left side
Hwy 101	34°7.474608 N	118°20.591124 W	Lane Departure	57	0.07	-0.04	
Hwy 101	34°7.695414 N	118°20.778996 W	Erratic Lane Positioning	58	-0.01	0.07	
Hwy 101	34°9.011310 N	118°22.433346 W	Erratic Lane Positioning	59	-0.05	-0.05	
Hwy 101	34°9.272658 N	118°22.843776 W	Erratic Lane Positioning	62	0.05	-0.03	
Hwy 101	34°9.381840 N	118°24.154080 W	Erratic Lane Positioning	6	-0.02	0.02	
Hwy 101	34°9.932946 N	118°29.547732 W	Erratic Lane Positioning	66	-0.03	-0.23	
Hwy 101	34°9.999630 N	118°29.688912 W	Lane Departure	65	-0.02	-0.04	Left side
Hwy 101	34°10.422702 N	118°33.587724 W	Erratic Lane Positioning	39	0.09	0.04	
Hwy 101	34°10.098774 N	118°34.953000 W	Lane Departure	40	-0.12	0.00	Left side
Hwy 101	34°10.090428 N	118°35.009070 W	Failure to Slow/Stop	37	0.02	0.03	
Hwy 101	34°9.074334 N	118°41.509104 W	Erratic Lane Positioning	67	-0.01	0.15	
Hwy 101	34°8.380128 N	118°43.876230 W	Lane Departure	68	-0.06	-0.04	
Hwy 101	34°9.248340 N	118°49.178928 W	Erratic Lane Positioning	68	0.03	-0.09	
Hwy 101	34°11.067816 N	118°55.543080 W	Lane Departure	71	-0.07	-0.16	Left side in a right curve
Hwy 101	34°12.042840 N	118°57.853704 W	Lane Departure	70	-0.04	-0.04	Left side in a right curve
Hwy 101	34°12.330138 N	118°59.311458 W	Lane Departure	70	-0.04	-0.27	Left side in a right curve
Hwy 101	34°14.709114 N	119°11.781648 W	Lane Departure	70	0.01	0.06	Left side
Hwy 101	34°15.082074 N	119°12.533658 W	Failure to Slow/Stop	56	0.03	-0.08	
Hwy 101	34°22.557000 N	119°28.541112 W	Lane Departure	70	-0.06	-0.17	Left side in a right curve
Hwy 101	34°22.637988 N	119°28.764348 W	Erratic Lane Positioning	66	0.00	-0.16	
Hwy 101	34°22.824540 N	119°28.905702 W	Erratic Lane Positioning	68	0.00	-0.01	
Hwy 101	34°23.794290 N	119°30.673446 W	Lane Departure	53	-0.02	-0.05	Lane departure, right side
Hwy 101	34°23.891946 N	119°30.745152 W	Lane Departure	57	0.00	-0.11	Lane departure, right side
Hwy 101	34°24.230772 N	119°31.731714 W	Lane Departure	65	0.05	0.09	Right side, during left curve
Hwy 101	34°24.956550 N	119°33.587982 W	Lane Departure	67	-0.01	0.23	Left side
Hwy 101	34°24.951714 N	119°34.718052 W	Lane Departure	67	0.03	-0.06	
Hwy 101	34°25.258068 N	119°37.324206 W	Lane Departure	67	0.03	-0.09	Left side, after lane change
Hwy 101	34°25.257174 N	119°37.478874 W	Lane Departure	68	0.03	-0.08	
Hwy 101	34°25.202556 N	119°38.519802 W	Lane Departure	68	0.05	-0.18	Left side, during right curve
Hwy 101	34°28.321824 N	120°11.385162 W	Erratic Lane Positioning	61	-0.01	-0.06	
Hwy 101	34°30.074442 N	120°13.701768 W	Lane Departure	68	0.07	0.25	Right side
Hwy 101	34°30.438108 N	120°13.582188 W	Lane Departure	69	-0.02	-0.27	Left side during right curve
Hwy 101	34°33.474924 N	120°11.527458 W	Lane Departure	69	0.02	-0.14	Left side during right curve
Hwy 101	34°41.169108 N	120°9.41846 W	Lane Departure	65	0.03	0.06	Right side during left curve, broken lane marking right side
Hwy 101	35°10.916394 N	120°42.060018 W	Lane Departure	68	-0.01	-0.20	Left side
Hwy 101	35°11.063196 N	120°42.082386 W	Lane Departure	68	0.03	-0.03	Left side
Hwy 101	35°11.636880 N	120°42.004236 W	Lane Departure	69	-0.03	0.10	Left side, vehicle is having a hard time tracking during curves
Hwy 101	35°12.410688 N	120°41.797674 W	Lane Departure	69	0.06	0.04	Right side
Hwy 101	35°14.553102 N	120°40.993818 W	Lane Departure	64	0.01	-0.17	Left side during right curve
Hwy 101	35°17.506134 N	120°39.357498 W	Lane Departure	69	-0.02	-0.25	Left side during right curve
Hwy 101	35°17.670090 N	120°38.447478 W	Other	69	0.00	-0.16	System turned off on an S curve
Hwy 101	35°17.759868 N	120°37.869900 W	Lane Departure	69	-0.05	0.04	Right side during left curve
Hwy 101	35°17.858760 N	120°37.679682 W	Lane Departure	68	0.00	0.04	Right side
Hwy 101	35°17.994960 N	120°37.562880 W	Lane Departure	66	-0.04	0.11	Left side
Hwy 101	35°19.287054 N	120°37.285764 W	Lane Departure	64	0.04	-0.12	Right side during right curve
Hwy 101	35°19.334892 N	120°37.284360 W	Lane Departure	64	0.01	-0.23	Left side
Hwy 101	35°21.859812 N	120°38.296200 W	Lane Departure	68	0.07	0.20	Once again, lane departure, going off road. Right side during left curve
Hwy 101	35°22.060104 N	120°38.444946 W	Lane Departure	69	0.09	-0.20	Left side during right curve
Hwy 101	35°39.112134 N	120°41.432748 W	Lane Departure	69	0.07	0.17	Right side during left curve
Hwy 101	35°49.577292 N	120°45.572382 W	Lane Departure	74	-0.06	-0.08	Left side during right curve
Hwy 101	35°50.337966 N	120°45.458904 W	Lane Departure	74	0.00	0.13	Right side during left curve
Hwy 101	35°50.454396 N	120°45.482472 W	Lane Departure	74	0.05	0.12	Right side during left curve
Hwy 101	35°53.191908 N	120°50.499696 W	Lane Departure	74	-0.04	-0.05	Left side after right curve
Hwy 101	35°57.675480 N	120°53.100960 W	Lane Departure	74	0.00	0.02	Right side
Hwy 101	35°57.885156 N	120°53.314854 W	Lane Departure	74	0.00	0.22	Right side
Hwy 101	35°58.173804 N	120°53.697348 W	Lane Departure	74	0.00	-0.17	Left side during right curve
Hwy 101	35°59.130846 N	120°54.188652 W	Lane Departure	74	0.01	0.06	Right side
Hwy 101	36°31.087686 N	121°26.468460 W	Lane Departure	66	-0.01	0.15	Road curved to the left and it just kept drifting to the right and crossed over the line
Hwy 101	36°49.256376 N	121°37.827150 W	Lane Departure	69	-0.04	0.03	Through that last turn, it could not keep up, crossed the line. Right side during left curve.
Hwy 101	37°8.603436 N	121°38.579238 W	Other	63	0.05	0.05	System disengaged without warning
Hwy 101	37°14.637648 N	121°46.323042 W	Erratic Lane Positioning	72	0.00	-0.03	Hugging right side near tractor trailer
I-680	37°33.703230 N	121°54.349764 W	Erratic Lane Positioning	18	-0.24	-0.04	Hugging left of the road
I-680	37°35.711232 N	121°52.337544 W	Erratic Lane Positioning	68	-0.02	-0.04	Right side of the lane about 15 seconds ago
I-680	37°36.009480 N	121°52.358382 W	Erratic Lane Positioning	72	0.04	-0.01	Left side of lane
I-680	37°36.214356 N	121°52.300290 W	Erratic Lane Positioning	72	-0.03	0.28	Right side of lane
I-680	37°37.366224 N	121°52.793538 W	Erratic Lane Positioning	74	0.09	-0.09	Left side of lane
I-680	37°54.776088 N	122°4.035534 W	Lane Departure	63	0.07	0.08	There was a lane departure in that last turn
I-680	37°50.830374 N	122°1.645062 W	Failure to Slow/Stop	53	-0.14	0.18	Late detection of lead vehicle

Figure 65: Subjective ratings during naturalistic evaluation of the 2020 Kia Telluride Image Source: AAA



Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-680	37°44.332638 N	121°57.116802 W	Other	58	0.08	-0.02	Slow to accelerate after lane change with no lead vehicle
I-680	37°43.642812 N	121°56.602134 W	Other	66	0.09	-0.06	Deceleration with no lead vehicle
I-580	37°42.058386 N	121°49.903560 W	Other	65	-0.01	-0.05	Deceleration with no lead vehicle
I-580	37°42.045894 N	121°48.436464 W	Other	62	0.00	-0.01	Deceleration with no lead vehicle
I-580	37°42.102342 N	121°46.056714 W	Other	57	-0.05	0.01	Late detection of tractor trailer ahead
I-580	37°42.167088 N	121°45.530460 W	Other	56	0.01	-0.03	Deceleration with no lead vehicle
I-580	37°42.148020 N	121°44.428560 W	Other	61	0.05	-0.01	Inappropriate acceleration into a curve
I-580	37°42.398238 N	121°43.749102 W	Other	64	0.01	0.02	Deceleration with no lead vehicle
I-580	37°42.787332 N	121°42.817836 W	Failure to Slow/Stop	66	0.12	0.06	Accelerating with lead vehicle ahead
I-580	37°43.266516 N	121°32.242032 W	Other	69	0.00	0.04	Tried to take exit lane
I-5	37°25.103280 N	121°9.117852 W	Erratic Lane Positioning	70	0.01	0.01	Slight "ping-ponging"
I-5	37°22.016214 N	121°7.420770 W	Erratic Lane Positioning	72	-0.02	-0.02	
I-5	36°56.924754 N	120°51.794382 W	Erratic Lane Positioning	71	0.03	-0.01	
I-5	36°56.181030 N	120°50.885304 W	Erratic Lane Positioning	71	0.03	-0.05	
I-5	36°48.198222 N	120°44.510286 W	Erratic Lane Positioning	73	-0.01	-0.03	
I-5	36°46.146468 N	120°43.100646 W	Erratic Lane Positioning	73	0.00	-0.05	
I-5	35°36.763590 N	119°39.053286 W	Other	78	0.05	-0.03	System Disengagement
I-5	35°31.995684 N	119°34.278186 W	Other	78	-0.01	0.02	System Disengagement about 20 seconds ago, very subtle and hard to notice
I-5	35°31.579620 N	119°33.824592 W	Other	78	-0.02	-0.01	System Disengagement about 20 seconds ago, very subtle and hard to notice
I-5	35°30.902046 N	119°33.087978 W	Other	78	0.00	-0.03	System will not engage
I-5	35°24.102744 N	119°24.089478 W	Erratic Lane Positioning	78	-0.06	-0.01	System wanted to abruptly take the exit and veered off the road
I-5	35°15.887130 N	119°13.342386 W	Other	78	0.05	-0.02	System Disengagement, not obvious
I-5	34°55.666830 N	118°55.721706 W	Lane Departure	71	0.08	-0.13	
I-5	34°50.370816 N	118°51.800466 W	Erratic Lane Positioning	70	0.07	-0.12	
I-5	34°50.249082 N	118°51.786186 W	Lane Departure	70	-0.02	-0.19	Left side during right curve
I-5	34°49.165182 N	118°52.815696 W	Erratic Lane Positioning	64	-0.02	0.06	
I-5	34°49.093002 N	118°52.890660 W	Erratic Lane Positioning	63	0.01	0.05	
I-5	34°49.083714 N	118°52.900002 W	Lane Departure	62	-0.01	-0.02	
I-5	34°38.058594 N	118°43.936242 W	Lane Departure	69	-0.02	-0.04	Right side during right curve
I-5	34°37.416810 N	118°43.136862 W	Lane Departure	69	0.00	-0.07	Right side during right curve
I-5	34°19.964904 N	118°30.459606 W	Lane Departure	68	0.02	-0.12	Left side during right curve
I-5	34°16.904796 N	118°27.418068 W	Erratic Lane Positioning	72	0.01	0.04	
I-5	34°13.768692 N	118°23.659614 W	Lane Departure	76	0.01	-0.01	
I-5	34°13.623594 N	118°23.359914 W	Lane Departure	73	-0.20	0.46	Right side
I-5	34°10.866336 N	118°18.843546 W	Lane Departure	39	-0.64	0.15	Left side
I-5	34°9.204096 N	118°17.165088 W	Lane Departure	56	0.03	0.03	
I-5	34°9.125376 N	118°16.955184 W	Lane Departure	60	0.59	-0.57	Right side during right curve
I-5	34°6.142836 N	118°15.000390 W	Other	10	-0.01	0.03	The steering wheel icon is green but the lane keeping icon is white
I-5	34°4.675710 N	118°13.764996 W	Failure to Slow/Stop	13	0.00	0.00	Car cut in front of vehicle, system slow to detect
I-5	34°4.569444 N	118°13.886982 W	Other	0	-0.06	0.00	System disengagement, sun angle likely a factor. Adaptive cruise is still operational.

Figure 66: Subjective ratings during naturalistic evaluation of the 2020 Kia Telluride Image Source: AAA



KIA Telluride	L2 Project Subjective Ratings										
	Driver 1		Driver 2	Driver 3	Driver 4		Driver 5		Driver 6		Totals/Avg
	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	
FCW warning timing	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1. Too late											0
2. Just right				1							1
3. Too early											0
LDW warning timing											
1. Too late	1	1	1					1	1	1	6
2. Just right				1	1	1	1				4
3. Too early											0
Comfort of ACC braking											
1. Too late				1						1	2
2. Just right		1	1		1	1	1	1	1		7
3. Too early	1										1
Comfort of ACC acceleration											
1. Too slow	1	1		1	1				1		5
2. Just right			1			1	1	1		1	5
3. Too fast											0
Lane Keeping Correction											
1. Too much correction											0
2. Just right	1	1		1		1	1			1	6
3. Not enough or no correction			1		1			1	1		4
Please rate the following from 1 to 5, where 5 is the best											
Awareness of system enabled	4	3	2	4	4	4	4	2	2	4	3.3
Awareness of system disengaged	2	3	2	3	1	4	3	2	3	2	2.5
Understanding of warnings	3	3	3	3	5	4	5	5	3	3	3.7
For ACC, which headway setting did you feel most comfortable using?											
1. Smallest	1	1	1	1			1	1			6
2. Middle					1	1			1	1	4
3. Largest											0
For Lane Centering, what was the tendency of the system											
1. Stay in the middle	1	1	1	1		1		1	1	1	8
2. Hug the left of the lane					1						1
3. Hug the right of the lane							1				1
For Lane Centering, did the system											
1. Compliment the drive	1	1	1	1	1	1	1				7
2. Neither enhance or detract								1	1	1	3
3. Fight the wheel											0
Overall Trust of the Level 2 system	4	4	3	3	3	4	3	3	3	3	3
Did the Level 2 system enhance the driving experience during highway driving?											
In Traffic?	n/a									n/a	
1. Yes		1	1		1	1	1				5
2. Neither enhance or detract								1	1		2
3. No				1							1
In Non-Traffic?							n/a	n/a			
1. Yes	1	1	1	1	1	1			1		7
2. Neither enhance or detract										1	1
3. No											0

Figure 67: Subjective ratings during naturalistic evaluation of the 2020 Kia Telluride Image Source: AAA



## 11.5 2020 Subaru Outback

Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
Hwy 101	34°25.007551 N	119°34.031796 W	Erratic Lane Positioning	56	0.06	0.02	Hugging left lane marker
Hwy 101	34°38.969566 N	120°13.820970 W	Lane Departure	65	0.01	-0.32	Lane departure left side
Hwy 101	34°29.293320 N	120°13.568118 W	Lane Departure	65	0.02	-0.01	Lane departure left side upon entering tunnel
Hwy 101	34°29.515476 N	120°13.562508 W	Lane Departure	66	0.01	0.28	Lane departure right side on new pavement
Hwy 101	34°29.682774 N	120°13.779870 W	Lane Departure	66	-0.01	-0.62	Lane departure left side gradual curve
Hwy 101	34°29.963580 N	120°13.813554 W	Lane Departure	67	0.05	-0.38	Lane departure left side gradual curve
Hwy 101	34°30.291350 N	120°13.580820 W	Lane Departure	70	-0.07	0.40	Lane departure vehicle followed exit lane
Hwy 101	34°31.149546 N	120°12.929754 W	Other	70	-0.03	-0.35	System disengagement without obvious cause
Hwy 101	34°31.41956 N	120°12.539322 W	Other	70	0.05	-0.19	System disengagement without obvious cause
Hwy 101	34°31.916814 N	120°11.785836 W	Erratic Lane Positioning	70	0.08	0.05	Hugging left lane marker
Hwy 101	34°34.168086 N	120°11.446650 W	Lane Departure	70	0.05	0.09	Lane departure right side on very slight curve
Hwy 101	34°34.934214 N	120°11.631174 W	Other	70	-0.07	-0.29	System disengagement upon entering slight right curve
Hwy 101	34°35.209806 N	120°11.476452 W	Other	71	0.00	0.27	System disengagement in slight left curve
Hwy 101	34°35.526162 N	120°11.627340 W	Other	71	-0.01	-0.26	System disengagement upon entering slight right curve
Hwy 101	34°37.293138 N	120°11.351592 W	Other	71	0.04	-0.14	System disengagement upon encountering merge lane
Hwy 101	35°38.348197 N	120°41.041486 W	Other	56	-0.07	0.08	System slowed for vehicle already in exit lane
Hwy 101	36°12.241458 N	121°8.014292 W	Other	59	0.03	0.02	System disengagement upon encountering fork for exit lane
Hwy 101	36°12.177230 N	121°8.507047 W	Erratic Lane Positioning	58	-0.04	0.15	Hugging right lane marker upon passing wide merge lane on right
Hwy 101	36°11.877459 N	121°9.045803 W	Other	65	0.02	-0.23	System disengagement within slight right curve
Hwy 101	36°25.863863 N	121°20.217813 W	Lane Departure	72	0.05	-0.26	Lane departure right side with simultaneous system disengagement
Hwy 101	36°26.093192 N	121°20.367557 W	Lane Departure	69	0.03	0.21	Lane departure left side with simultaneous system disengagement with merge lane alongside
Hwy 101	36°31.397898 N	121°27.735822 W	Lane Departure	71	-0.02	-0.03	Lane departure right side upon encountering exit lane
Hwy 101	36°33.141590 N	121°30.018346 W	Lane Departure	71	0.00	-0.03	Lane departure left side without obvious cause
Hwy 101	36°48.095525 N	121°39.611161 W	Lane Departure	66	0.01	-0.13	Lane departure right side upon passing wide merge lane on right
Hwy 101	36°49.529242 N	121°37.698798 W	Erratic Lane Positioning	68	-0.01	0.18	Hugging left lane marker in slight left curve
Hwy 101	36°51.749850 N	121°37.057782 W	Lane Departure	64	-0.05	-0.23	Lane departure left side with simultaneous system disengagement in slight right curve
Hwy 101	36°51.622698 N	121°36.547626 W	Erratic Lane Positioning	65	0.04	-0.79	Hugging left lane marker in slight left curve
Hwy 101	36°51.686034 N	121°35.041320 W	Lane Departure	67	-0.02	-0.23	Lane departure left side without obvious cause
Hwy 101	36°51.745230 N	121°34.692900 W	Lane Departure	68	-0.11	0.33	Lane departure right side on slight left curve
Hwy 101	36°55.698420 N	121°32.826624 W	Lane Departure	66	-0.10	0.17	Lane departure left side with guardrail alongside
Hwy 101	37°8.382618 N	121°38.363844 W	Other	64	0.12	0.06	System having difficulty recognizing lane markers (there is also black striping) and will not engage
Hwy 101	37°17.891557 N	121°48.707339 W	Erratic Lane Positioning	71	0.00	0.10	"Ping-ponging" within lane
Hwy 101	37°20.276149 N	121°50.054524 W	Lane Departure	54	0.01	-0.02	Lane departure left side with barrier alongside
I-680	37°30.345552 N	121°56.054676 W	Erratic Lane Positioning	0	0.03	0.00	System favoring right side of lane in traffic
I-680	37°35.403596 N	121°52.215109 W	Erratic Lane Positioning	50	0.00	0.16	System hugging left side with barrier alongside
I-680	37°42.225979 N	121°55.430308 W	Erratic Lane Positioning	65	0.03	0.04	System hugging left side without obvious cause
I-680	37°48.936855 N	121°59.592683 W	Other	59	-0.01	0.03	System disengagement upon encountering faded lane markers
I-680	37°53.896984 N	122°4.281123 W	Lane Departure	63	-0.10	0.19	System hugging left lane marker before crossing markers on bridge with simultaneous disengagement
I-680	37°53.129784 N	122°3.317876 W	Lane Departure	70	-0.03	0.12	Lane departure left side upon encountering repaved roadway
I-680	37°52.829988 N	122°3.012798 W	Other	71	0.08	-0.01	System disengagement while simultaneous left side lane departure upon encountering overpass
I-680	37°47.713623 N	121°59.079360 W	Erratic Lane Positioning	61	0.00	-0.05	System hugging right lane marker with vehicle alongside
I-680	37°46.602108 N	121°58.509264 W	Other	71	0.02	0.06	System will not engage. Sun angle likely a factor.
I-680	37°45.854916 N	121°58.100592 W	Other	71	0.04	-0.02	System still will not engage. Sun angle likely a factor.
I-680	37°45.118192 N	121°57.619000 W	Other	71	0.02	-0.01	System still will not engage. Sun angle likely a factor.
I-680	37°43.567818 N	121°56.547342 W	Erratic Lane Positioning	66	-0.01	-0.03	System hugging right shoulder without obvious cause
I-580	37°42.818244 N	121°42.748980 W	Lane Departure	64	0.04	-0.02	Lane departure right side without obvious cause
I-580	37°42.962632 N	121°42.413827 W	Erratic Lane Positioning	65	0.00	-0.10	System hugging right lane marker without obvious cause
I-580	37°43.940346 N	121°37.817328 W	Lane Departure	65	-0.05	-0.04	Lane departure left side upon passing underneath overpass
I-5	37°44.157088 N	121°33.235834 W	Other	71	-0.01	-0.04	System will not engage. Sun angle likely a factor.
I-5	37°40.803494 N	121°28.228093 W	Erratic Lane Positioning	64	0.08	0.01	System hugging right shoulder. Sun angle likely a factor.
I-5	37°40.712028 N	121°28.076562 W	Erratic Lane Positioning	63	0.00	-0.02	System hugging right shoulder in a continuation of last event. Sun angle likely a factor.
I-5	37°40.670147 N	121°28.007460 W	Erratic Lane Positioning	59	0.01	-0.04	System hugging right shoulder in a continuation of last event. Sun angle likely a factor.
I-5	37°40.542366 N	121°27.796621 W	Erratic Lane Positioning	57	0.02	-0.04	System hugging right shoulder in a continuation of last event. Sun angle likely a factor.
I-5	37°40.452077 N	121°27.648197 W	Other	58	0.01	0.08	System attempted to follow exit lane and disengaged
I-5	37°38.767008 N	121°24.868500 W	Other	69	0.01	-0.02	System attempted to follow exit lane and disengaged
I-5	37°35.647938 N	121°20.281998 W	Lane Departure	69	-0.04	-0.03	Lane departure left shoulder. Sun angle likely a factor.
I-5	37°35.647938 N	121°20.281998 W	Erratic Lane Positioning	69	-0.04	0.02	System hugging right shoulder. Sun angle likely a factor.
I-5	37°34.087650 N	121°18.260472 W	Other	68	-0.01	-0.06	System disengaged. Sun angle likely a factor.
I-5	37°32.537937 N	121°16.246935 W	Other	69	0.02	-0.04	System will not engage. Sun angle likely a factor.
I-5	37°31.748897 N	121°15.258966 W	Other	69	-0.06	-0.05	System still will not engage. Sun angle likely a factor.
I-5	37°14.805670 N	121°5.353996 W	Erratic Lane Positioning	75	-0.04	-0.02	System hugging right lane marker while passing under overpass. Sun angle likely a factor.
I-5	37°3.544692 N	120°58.340694 W	Lane Departure	76	-0.02	-0.08	Lane departure right side. Changing position of lane marker and/or sun angle likely factors.
I-5	36°57.853770 N	120°52.926283 W	Erratic Lane Positioning	76	-0.01	-0.01	System hugging left lane shoulder. Sun angle likely a factor.
I-5	36°44.042040 N	120°41.654070 W	Lane Departure	75	0.02	0.03	Lane departure right side. Sun angle likely a factor.
I-5	35°53.314446 N	119°51.919266 W	Erratic Lane Positioning	76	0.08	-0.01	System hugging left lane marker with vehicle alongside
I-5	35°34.633314 N	119°37.099206 W	Other	76	-0.10	-0.02	System will not engage.
I-5	35°33.453393 N	119°35.862499 W	Erratic Lane Positioning	76	-0.03	0.01	System hugging right lane marker with tractor trailer alongside
I-5	35°32.416579 N	119°34.732901 W	Erratic Lane Positioning	76	0.03	0.01	System "ping-ponging" within lane
I-5	35°31.154797 N	119°33.362881 W	Erratic Lane Positioning	76	-0.06	-0.05	System hugging right shoulder

Figure 68: Subjective ratings during naturalistic evaluation of the 2020 Subaru Outback Image Source: AAA



Location	Latitude	Longitude	Event Type	Speed (mph)	Longitudinal Acc (G)	Lateral Acc (G)	Comments
I-S	35°31.102896 N	119°33.307122 W	Lane Departure	74	0.04	0.10	Lane departure left side resulting from "ping-ponging" in continuation from last event
I-S	35°30.972882 N	119°33.165210 W	Erratic Lane Positioning	70	-0.01	0.01	System hugging left lane marker with vehicle passing alongside
I-S	35°30.727398 N	119°32.898252 W	Erratic Lane Positioning	68	0.03	0.09	System hugging left lane marker with vehicle passing alongside
I-S	35°30.580398 N	119°32.737644 W	Lane Departure	68	-0.04	-0.03	Lane departure right shoulder. Pavement darker than adjacent lane.
I-S	35°30.458508 N	119°32.604888 W	Lane Departure	68	-0.02	-0.02	Lane departure right shoulder. Pavement darker than adjacent lane.
I-S	35°26.529558 N	119°27.411090 W	Erratic Lane Positioning	76	0.07	-0.15	System hugging right lane marker with tractor trailer alongside
I-S	35°24.936282 N	119°25.228212 W	Lane Departure	76	0.03	0.07	Lane departure left lane marker with vehicle passing alongside. Pavement darker than adjacent lane.
I-S	35°19.792639 N	119°18.058679 W	Lane Departure	76	0.00	0.03	Lane departure left lane marker. Dark strips down lane.
I-S	35°19.733027 N	119°17.973439 W	Lane Departure	76	0.02	-0.09	Lane departure right side resulting from "ping-ponging" in continuation from last event
I-S	35°14.803582 N	119°12.189099 W	Other	76	0.02	-0.01	System will not engage. Dark strips down lane.
I-S	35°9.542437 N	119°6.488746 W	Erratic Lane Positioning	77	-0.04	-0.02	System hugging right lane marker with tractor trailer alongside
I-S	35°1.158750 N	118°57.491184 W	Other	77	-0.03	-0.06	System disengaged upon encountering faded lane markers and older pavement
I-S	34°59.689890 N	118°56.892198 W	Other	76	-0.03	-0.01	System will not engage. Worn lane markers and older pavement
I-S	34°55.951782 N	118°55.854582 W	Other	71	0.00	0.31	System disengagement without obvious cause
I-S	34°55.566468 N	118°55.725186 W	Lane Departure	71	-0.02	0.18	Lane departure right side and simultaneous system disengagement without obvious cause
I-S	34°55.392582 N	118°55.611192 W	Lane Departure	70	-0.02	0.01	Lane departure left side and simultaneous system disengagement without obvious cause
I-S	34°55.034561 N	118°55.510277 W	Lane Departure	71	-0.01	0.05	Lane departure right side and simultaneous system disengagement without obvious cause
I-S	34°54.607046 N	118°55.444166 W	Lane Departure	63	0.06	0.02	Lane departure right side and simultaneous system disengagement with patched pavement alongside
I-S	34°50.173158 N	118°51.804312 W	Other	75	0.01	-0.14	System disengagement while passing under overpass
I-S	34°49.179977 N	118°52.799453 W	Other	75	0.02	0.02	System will not engage. Sun angle likely a factor.
I-S	34°19.997087 N	118°30.481111 W	Lane Departure	76	0.07	-0.31	Lane departure left side with simultaneous system disengagement
I-S	34°16.783230 N	118°27.346830 W	Other	72	-0.03	0.07	System disengagement. Faded lane markers possible cause.
I-S	34°16.274364 N	118°26.890686 W	Other	64	-0.06	0.04	System disengagement. Faded lane markers possible cause.
I-S	34°14.797464 N	118°25.471188 W	Other	69	0.03	0.03	System disengagement. Faded lane markers possible cause.
I-S	34°13.354770 N	118°22.221636 W	Erratic Lane Positioning	70	0.04	0.14	System hugging left lane marker without obvious cause.
I-S	34°13.311387 N	118°21.905656 W	Other	68	-0.01	0.07	System disengagement without obvious cause
I-S	34°12.693829 N	118°20.881029 W	Erratic Lane Positioning	74	0.03	-0.05	System hugging right lane marker. Shadow casted over roadway possible cause.
I-S	34°12.353972 N	118°20.573202 W	Other	56	-0.04	-0.04	System disengagement without obvious cause
I-S	34°11.590593 N	118°19.771899 W	Other	32	0.02	-0.05	System will not stay engaged in traffic
I-S	34°10.923942 N	118°18.892326 W	Other	41	0.03	0.01	System disengagement in moderate traffic.
I-S	34°10.680725 N	118°18.593874 W	Other	42	-0.02	0.01	System disengagement in moderate traffic.
I-S	34°9.891480 N	118°17.821326 W	Other	48	-0.12	-0.02	System disengagement in moderate traffic.
I-S	34°9.335062 N	118°17.374926 W	Other	61	-0.02	0.10	System disengagement without obvious cause
I-S	34°9.125607 N	118°16.965045 W	Erratic Lane Positioning	65	0.12	0.16	System hugging left lane marker while passing under overpass

Figure 69: Subjective ratings during naturalistic evaluation of the 2020 Subaru Outback Image Source: AAA



Subaru Outback	L2 Project Subjective Ratings										
	Driver 1		Driver 2	Driver 3	Driver 4		Driver 5		Driver 6		Totals/Avg
	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	LA to SF	SF to LA	
FCW warning timing	n/a	n/a	n/a		n/a	n/a				n/a	
1. Too late											0
2. Just right				1			1		1		3
3. Too early								1			1
LDW warning timing											
1. Too late		1	1								2
2. Just right	1			1	1	1	1	1	1	1	8
3. Too early											0
Comfort of ACC braking											
1. Too late			1								1
2. Just right	1	1		1	1	1	1	1	1	1	9
3. Too early											0
Comfort of ACC acceleration											
1. Too slow		1									1
2. Just right	1		1	1	1	1	1	1	1	1	9
3. Too fast											0
Lane Keeping Correction											
1. Too much correction				1				1			2
2. Just right						1	1		1	1	4
3. Not enough or no correction	1	1	1		1						4
Please rate the following from 1 to 5, where 5 is the best											
Awareness of system enabled	4	4	3	3	3	5	5	5	5	5	4.2
Awareness of system disengaged	4	3	4	3	2	4	5	5	5	5	4
Understanding of warnings	3	3	3	3	2	4	5	5	4	4	3.6
For ACC, which headway setting did you feel most comfortable using?											
1. Smallest	1	1	1	1			1	1			6
2. Middle						1			1	1	3
3. Largest					1						1
For Lane Centering, what was the tendency of the system											
1. Stay in the middle	1	1		1	1	1	0.5	1	1	1	8.5
2. Hug the left of the lane			0.5				0.5				1
3. Hug the right of the lane			0.5								0.5
For Lane Centering, did the system											
1. Compliment the drive	1	1			1	1	0.5		1		5.5
2. Neither enhance or detract				1				1		1	3
3. Fight the wheel			1				0.5				1.5
Overall Trust of the Level 2 system	4	4	2	3	3	4	4	4	4		4
Did the Level 2 system enhance the driving experience during highway driving?											
In Traffic?								n/a			
1. Yes	1				1	1	1		1	1	6
2. Neither enhance or detract		1		1							2
3. No			1								1
In Non-Traffic?											
1. Yes	1	1			1	1	1	1	1		7
2. Neither enhance or detract				1						1	2
3. No			1								1

Figure 70: Subjective ratings during naturalistic evaluation of the 2020 Subaru Outback Image Source: AAA



## 12 Bibliography

- [1] SAE International, "Taxonomy and Definitions for Terms Related to Driving Automation Systems for On-Road Motor Vehicles," 2018-06.
- [2] National Highway Traffic Safety Administration, "Traffic Safety Facts Annual Report Tables," 23 April 2019. [Online]. Available: <https://cdan.nhtsa.gov/tsftables/tsfar.htm#>. [Accessed 19 November 2019].
- [3] A. Benson, B. Tefft, A. M. Svancara and W. Horrey, "Potential Reduction in Crashes, Injuries, and Deaths from Large-Scale Deployment of Advanced Driver Assistance Systems," *AAA Foundation for Traffic Safety*, 2018.
- [4] Insurance Institute of Highway Safety, "Advanced Driver Assistance," May 2019. [Online]. Available: <https://www.iihs.org/topics/advanced-driver-assistance>. [Accessed 20 November 2019].
- [5] H. Clark, A. C. McLaughlin and J. Feng, "Situational Awareness and Time to Takeover: Exploring an Alternative Method to Measure Engagement with High-Level Automation," in *Proceedings of the Human Factors and Ergonomics Society*, 2017.
- [6] N. Dunn, T. Dingus and S. Soccolich, "Understanding the Impact of Technology: Do Advanced Driver Assistance and Semi-Automated Vehicle Systems Lead to Improper Driving Behavior?," *AAA Foundation for Traffic Safety*, 2019.